

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 5668X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH FRONT DOOR ASSY (WCP)	TO REPAIR SEE LABOUR	680.00	-
1	LH FRONT DOOR W/STRIP (WCP)	NOT NECESSARY	75.00	-
1	LH FRONT DOOR TAPE (WCP)	NOT FITTED	25.00	-
1	LH FRONT DOOR OUTER HANDLE (WCP)	SERVICEABLE	135.00	-
1	LH SLIDING DOOR ASSY (WCP)	BADLY DENTED	750.00	750.00
1	LH SLIDING DOOR OUTER HANDLE (WCP)	BROKEN	85.00	85.00
1	LH SLIDING DOOR LOWER ROLLER HINGE LH (WCP)	SERVICEABLE	75.00	-
1	DOOR CENTRE OUTER PILLAR (WCP)	BADLY DENTED	300.00	300.00
1	REAR BUMPER FASCIA (WCP)	GRAZED	400.00	400.00
1	REAR WHEEL CAP (WCP)	CUT	105.00	105.00
1	SET REAR BUMPER CLIPS (WCP)	NECESSARY	20.00	20.00
	COST PLUS 10%		265.00	166.00
			2,915.00	1,826.00
	SPECIAL NETT ITEMS			
1	LH FRONT DOOR COMPANY STICKER (SN)	NECESSARY	28.00	28.00
			28.00	28.00
	LABOUR			
	CUT OUT, RENEW, KNOCKING, WELDING, STRAIGHTEN & RE-ALIGN LH DOOR CENTRE OUTER PILLAR, LH RUNNING BOARD PANEL, LH REAR FENDER, ALL AFFECTED PARTS & ETC. INCLUSIVE OF THE REPAIR OF LH FRONT DOOR ASSY.		1,200.00	880.00
	REMOVE & REFIX LH FRONT DOOR ASSY, DOOR GLASS, GLASS REGULATOR, POWER WINDOW MOTOR ASSY CENTRE LOCKING SYSTEM, LOCK MECHANISM, DOOR BOARD & OUTER HANDLE, LEFT SLIDING DOOR ASSY, LOCKING MECHANISM, ROLLER HINGE, ALL AFFECTED PARTS & ETC.		280.00	100.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,200.00	800.00
	CHECK ALL WIRING & LIGHTING AFTER REPAIRS.		35.00	20.00
			2,715.00	1,800.00
	GRAND TOTAL		5,658.00	3,654.00

Report Ref No. CS/GAI20005766/Uvf3e2





RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		2,900.00
LESS EXCESS		-700.00
NETT LIABILITY		2,200.00

Report Ref No. CS/GAI20005766/Uvf3e2

CHUA KANG SENG
Licensed Appraiser