

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005770/KGA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : EX8899K	Insured Vehicle No :	SHC3351G
Date of Loss: 14/05/2020	Nature of Claim: TP	Claim No: MCT20050087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EX8899K	Engine No:	2ARF244222
Make & Model:	TOYOTA LEXUS, 2.5 ES250 AUTO (A)	Chassis No:	JTHBJ1GG002094169
Reg. Date:	08/11/2016 (Man. Year: 2016)	Odometer:	49882 km
Colour:	Metallic Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,648.39	1,674.90	973.49	36.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	560.00	170.00	23.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	3,378.39	2,234.90	1,143.49	33.85
Approved Total (Overridden) (\$)		1,750.00		
(\$)	3,378.39	1,750.00	1,628.39	48.20
+ GST 7.00/7.00% (\$)	236.49	122.50	113.99	48.20
Nett Amount (\$)	3,614.88	1,872.50	1,742.38	48.20
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	10/06/2020	
Date Inspected:	10/06/2020 Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2020)
Parts:	143	TOYOTA LEXUS 2.5 ES250 AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EX8899K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	*Check	935.80 FL	*- FL
2	1		*FRONT NO PLATE GARNISH	Dented	135.60 FL	*135.60 FL
3	1		*FRONT GRILLE	Cracked	998.20 FL	*998.20 FL
4	1		*FRONT GRILLE CHROME	Cracked	312.90 FL	*312.90 FL
5	1		*FRONT GRILLE LOGO	Necessary	364.30 FL	*364.30 FL
6	1		*FRONT BUMPER SPONGE	*Check	140.30 FL	*- FL
7	1		*FRONT NO PLATE WITH BOX	Bent	50.00 FS	*45.00 FS
					Sub Total (\$\$)	2,937.10
					- List Item Discount on L Items 10.00/10.00% (\$\$)	288.71
					Total Parts (\$\$)	2,648.39
						1,674.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRING FRONT BUMPER PARKING SENSOR	New	30.00	30.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	300.00	250.00
3	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	400.00	280.00
Gross Labour Cost (\$\$)			730.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >