

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06170

Vehicle Insured : SHC3351G
Accident Date : 14-May-2020

Date : 15-May-2020

Our Ref : 020050 (III) / CHAN

PAGE : 1

OH TIAN TECK
61 CHARTWELL DRIVE
Singapore 558755

Not Authorised
Penny After Pairs
6/15/8? *2 days*

ESTIMATED COST OF REPAIR FOR LEXUS ES250 2.5A EX8899K

1 pc Front bumper fascia	935.80	?
1 pc Front no.plate garnish	135.60	✓
1 pc Front grille	998.20	✓
1 pc Front grille chrome	312.90	✓
1 pc Front grille logo	364.30	✓
1 pc Front bumper sponge	140.30	?
	2,887.10	
Less 10% :	288.71	
	2,598.39	45% sn
1 pc Front no.plate with box	50.00	sn
To rewiring front bumper parking sensor	30.00	✓
To putty and spray replaced parts	250/ 300.00	
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	280/ 400.00	
Total :	S\$ 3,378.39	

Singapore Dollars Three Thousand Three Hundred and Seventy Eight and Cents Thirty Nine Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: