

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC3351G

Accident Date : 14-May-2020

Our Ref : 020050 (III) / CHAN

OH TIAN TECK

61 CHARTWELL DRIVE

Singapore 558755

No. : 06170

Date : 15-May-2020

PAGE : 1

ESTIMATED COST OF REPAIR FOR LEXUS ES250 2.5A EX8899K

=====

1 pc Front bumper fascia	935.80
1 pc Front no.plate garnish	135.60
1 pc Front grille	998.20
1 pc Front grille chrome	312.90
1 pc Front grille logo	364.30
1 pc Front bumper sponge	140.30

2,887.10

Less 10% : 288.71

1 pc Front no.plate with box

2,598.39

50.00 sn

To rewiring front bumper parking
sensor

30.00

To putty and spray replaced parts

300.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00

Total : S\$ 3,378.39

=====

Singapore Dollars Three Thousand Three Hundred
and Seventy Eight and Cents Thirty Nine Only