

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005771/R1DS3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700086626

Claimant
Vehicle No : SLZ112G **Insured Vehicle No :** SLJ5544U

Date of Loss: 10/05/2020 Nature of Claim: TP Claim No: 7203586165SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ112G	Engine No:	A342J432N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR (A)	Chassis No:	WBA3A12070J720092
Reg. Date:	28/03/2013 (Man. Year: 2013)	Odometer:	131939 km
Colour:	Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,716.92	4,510.88	9,206.04	67.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	900.00	1,100.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,716.92	5,410.88	10,306.04	65.57
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	15,716.92	4,300.00	11,416.92	72.64
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		4,540.00		

INSPECTION

Date of Assignment: 18/05/2020

Date Inspected: 03/06/2020 Inspected At:

Mtm Performance Auto Pte Ltd
48 TOH GUAN ROAD EAST #01-115
ENTERPRISE HUB
Singapore 608586

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER M-SPORT	Scratched	1,332.00 F	*1,332.00 FL
2	1		*FRONT LIP M-SPORT	Cracked	1,420.00 FS	*700.00 FS
3	1		*LEFT HEAD LAMP	Scratched	2,280.00 F	*2,066.00 FL
4	1		*LEFT FENDER FRONT	Repair	751.20 F	*- FL
5	1		*FRONT RE-ENFORCEMENT BAR	Not Necessary	406.60 F	*- FL
6	1		*FRONT LEFT LOCK	Not Necessary	94.20 F	*- FL
7	1		*FRONT PDC SENSOR	Missing	395.90 FS	*250.00 FS
8	1		*FRONT LEFT FOG LAMP	Cracked	295.30 F	*295.30 FL
9	1		*FRONT LEFT FOG LAMP GRILLE	Cracked	96.30 F	*55.00 FL
10	1		*FRONT LEFT FENDER COVER	Not Necessary	125.20 F	*- FL
11	1		*FRONT LEFT AND RIGHT RETAINER	Not Necessary	85.60 F	*- FL
12	1		*FRONT LEFT HEAD LAMP MODULE	Not Necessary	1,995.55 F	*- FL
13	1		*FRONT LEFT DIS LIGHTBULB	Not Necessary	311.40 F	*- FL
14	1		*BONNET	Not Necessary	1,370.67 F	*- FL
15	1		*BUTTERFLY	Not Necessary	160.50 F	*- FL
16	1		*BONNET HOOK	Not Necessary	27.90 F	*- FL
17	1		*FRONT LEFT BOTTOM RUBBER GARNISH	Not Necessary	112.35 F	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	180.85 F	*- FL
19	1		*SET WIPER WASHER FRONT LEFT OF WHOLE	Not Necessary	171.20 F	*- FL
20	1		*FRONT GRILLE	Not Necessary	160.00 F	*- FL
21	1		*RADIATOR	Not Necessary	838.90 F	*- FL
22	1		*CONDENSER	Not Necessary	1,105.30 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,716.92	4,698.30
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	187.42
Total Parts (\$)	13,716.92	4,510.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	1,000.00	400.00
2	SPRAY PART	New	1,000.00	500.00
Gross Labour Cost (\$)			2,000.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >