

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005775/AGA3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994047

Claimant
Vehicle No : SFS989B **Insured Vehicle No :** SLJ2946M

Date of Loss: 12/05/2020 Nature of Claim: TP Claim No: 0835342886SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFS989B		
Make & Model:	AUDI A4 AVANT, 2.0 TFSI (A)	Engine No:	CDN339280
Reg. Date:	30/07/2013 (Man. Year: 2013)	Chassis No:	WAUZZZ8K7DA232633
Colour:	Grey	Odometer:	90278 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,778.00	6,728.00	2,050.00	23.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,522.00	2,902.00	2,620.00	47.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,300.00	9,630.00	4,670.00	32.66
+ GST 7.00/7.00% (S\$)	1,001.00	674.10	326.90	32.66
Nett Amount (S\$)	15,301.00	10,304.10	4,996.90	32.66
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/05/2020

Date Inspected: 22/05/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,581.00 FS	*2,581.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	215.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -LOWER CENTRE	Not Necessary	310.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -UPPER CENTRE	Not Necessary	183.00 FS	*- FS
6	1		*VENT GRILLE -RH	Cut	545.00 FS	*545.00 FS
7	1		*FRONT WHEEL SPOILER -RH	*Check	48.00 FS	*- FS
8	1		*FRONT BUMPRT GUIDE SECTION -RH	*Check	34.00 FS	*- FS
9	1		*FRONT FENDER -RH	Dented	932.00 FS	*932.00 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	*Check	54.00 FS	*- FS
11	1		*FRONT FENDER BRACKET -RH FRONT	Damaged	50.00 FS	*50.00 FS
12	1		*DEFORMATION ELEMENT BRACKET -RH REAR	*Check	46.00 FS	*- FS
13	1		*FRONT FENDER BRACE -RH LOWER	*Check	112.00 FS	*- FS
14	1		*STONE CHIP GUARD	Necessary	69.00 FS	*69.00 FS
15	1		*ADHESIVE TAPE	*Check	52.00 FS	*- FS
16	1		*WHEEL HOUSING LINER	Deformed	226.00 FS	*226.00 FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	*Check	42.00 FS	*- FS
18	1		*HEADLIGHT MOUNTING -RH	*Check	112.00 FS	*- FS
19	1		*HEADLAMP BRACKET -RH	*Check	100.00 FS	*- FS
20	1		*HEADLIGHT -RH	Cracked	2,208.00 FS	*2,208.00 FS
21	1		*LIFT CYLINDER-RH	Not Necessary	198.00 FS	*- FS
22	1		*S-LINE INSCRIPTION	Necessary	117.00 FS	*117.00 FS
23	1		*FRONT RIM -RH (NPA)	Not Necessary	0.00 FS	*- FS
24	1		*SUNDRIES	*Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,778.00** **6,728.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT CONMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT PREP-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT TO RENEW RHS FRONT RIM	New	520.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,522.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >