

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005778/AEA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800090391

Claimant
Vehicle No : GBC784G **Insured Vehicle No :** SGW6722G

Date of Loss: 16/05/2020 Nature of Claim: TP Claim No: 9733958042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC784G		Engine No:	1KD2093763
Make & Model:	TOYOTA HIACE, 2.5 (M)		Chassis No:	JTFHT02P900073072
Reg. Date:	08/04/2011 (Man. Year: 2011)		Odometer:	217060 km
Colour:	Grey			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,688.00	2,885.75	4,802.25	62.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	2,060.00	2,510.00	54.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,258.00	4,945.75	7,312.25	59.65
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	12,258.00	3,900.00	8,358.00	68.18
+ GST 7.00/7.00% (S\$)	858.06	273.00	585.06	68.18
Nett Amount (S\$)	13,116.06	4,173.00	8,943.06	68.18
+ Car Rental (5.0 x S\$120.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,822.45		

INSPECTION

Date of Assignment: 18/05/2020

Date Inspected: 19/05/2020 Inspected At:

SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom
Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	458.00 FL	*458.00 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	178.00 FL	*65.00 FL
3	1		*FRONT BUMPER FOG LAMP COVER LH	Deformed	154.00 FL	*154.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	120.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT TOP	Not Necessary	289.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT LOWER	Not Necessary	548.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	215.00 FL	*- FL
8	1		*FRONT CORNER PANEL LH	Dented	189.00 FL	*189.00 FL
9	1		*CENTRE GRILLE	Cracked	384.00 FL	*384.00 FL
10	1		*CENTRE GRILLE BASE	Not Necessary	214.00 FL	*- FL
11	1		*SIDE MIRROR LH	Not Necessary	389.00 FL	*- FL
12	1		*HEADLAMP LH	Cracked	450.00 FL	*450.00 FL
13	1		*HEADLAMP BRACKET	Cracked	41.00 FL	*41.00 FL
14	1		*FRONT WINDSCREEN RUBBER	Not Necessary	254.00 FL	*- FL
15	1		*BONNET	Repair	598.00 FL	*- FL
16	1		*BONNET HINGE	Not Necessary	154.00 FL	*- FL
17	1		*BONNET LOGO	Necessary	89.00 FL	*89.00 FL
18	1		*BONNET LOCK	Not Necessary	168.00 FL	*- FL
19	1		*WIREHARNES	Not Necessary	584.00 FL	*- FL
20	1		*FRONT DOOR LH	Dented	1,208.00 FL	*1,208.00 FL
21	1		*FRONT DOOR INNER TRIM	Not Necessary	445.00 FL	*- FL
22	1		*FRONT DOOR FRIM RUBBER	Not Necessary	68.00 FL	*- FL
23	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	154.00 FL	*- FL
24	1		*FRONT DOOR CONNER RUBBER	Not Necessary	115.00 FL	*- FL
25	1		*FRONT DOOR HINGE	Not Necessary	156.00 FL	*- FL
26	1		*FRONT DOOR STEP GARNISH	Cut	189.00 FL	*189.00 FL
27	1		*FRONT DOOR STEP PANEL	Not Necessary	511.00 FL	*- FL
28	1		*FRONT DOOR PILLAR (INNER)	Repair	548.00 FL	*- FL
29	1		*FRONT DOOR PILLAR (OUTER)	Dented	554.00 FL	*554.00 FL
30	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
31	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
32	1		*FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
33	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
34	1		*SET DASHBOARD CLIPS	Not Necessary	60.00 FS	*- FS
35	1		*FRONT DOOR SEALANT	Not Necessary	60.00 FS	*- FS
36	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
37	1		*FRONT DOOR PILLAR (INNER) SEALANT	Not Necessary	60.00 FS	*- FS
38	1		*FRONT DOOR PILLAR (OUTER) SEALANT	Not Necessary	60.00 FS	*- FS
39	1		*COMPANY STICKER	Necessary	50.00 FS	*20.00 FS
40	1		*BRAKE OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,044.00	3,831.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,356.00	945.25
Total Parts (\$\$)	7,688.00	2,885.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,500.00	900.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	700.00
3	TUFF COAT	New	200.00	50.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	400.00	80.00
6	TRANSFER FRONT DOOR MECHANISM LH	New	150.00	80.00
7	REMOVE AND REFIX AIRCON COOLING COIL AND REFILL AIRCON GAS	New	250.00	0.00
8	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	New	450.00	220.00
9	REFOCUS HEADLAMP BEAM	New	120.00	0.00
10	REMOVE AND REFIX FRONT WINDSCREEN	New	150.00	0.00
Gross Labour Cost (\$\$)			4,570.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >