

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005793/ABA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994037

Claimant
Vehicle No : SJM3212Z **Insured Vehicle No :** SJG204Z

Date of Loss: 08/05/2020 Nature of Claim: TP Claim No: 3839685169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM3212Z		
Make & Model:	HONDA STREAM, 1.8 L (A)	Engine No:	HIDDEN
Reg. Date:	01/12/2008 (Man. Year: 2008)	Chassis No:	JHMRN68408S205832
Colour:	Silver	Odometer:	301441 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,874.20	925.84	1,948.36	67.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	430.00	670.00	60.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,974.20	1,355.84	2,618.36	65.88
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	3,974.20	1,050.00	2,924.20	73.58
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
Nett Liability (S\$)		1,290.00		

INSPECTION

Date of Assignment: 18/05/2020

Date Inspected: 18/05/2020 Inspected At:

Leang Automotive (Kaki Bukit)
AUTOBAY @ KAKI BUKIT 1 KAKI
BUKIT AVE 6 #01-68
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Dented	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*FRONT BUMPER	Deformed	638.00 F	*638.00 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	41.00 F	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	218.80 F	*- FL
7	1		*FRONT GRILLE	Cut	208.10 F	*208.10 FL
8	1		*FRONT GRILLE CHROME MOULDING	Cut	210.30 F	*210.30 FL
9	1		*FRONT GRILLE LOGO	Necessary	23.40 F	*23.40 FL
10	1		*FRONT GRILLE CLIPS	Necessary	10.00 F	*10.00 FL
11	2		*HEADLAMP	Not Necessary	1,361.60 F	*- FL
12	2		*HEADLAMP LOWER BRACKET	Not Necessary	73.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,874.20	1,149.80
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	223.96
Total Parts (\$)	2,874.20	925.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTING	New	500.00	200.00
3	WIRING	New	100.00	30.00
Gross Labour Cost (S\$)			1,100.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >