Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005795/KVF3E2

Date: 03/06/2020

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer:

Policy No: Pte. Ltd.

DMCVSN30855019000

Claimant Vehicle SLV2649H

Insured Vehicle No:

GBG3870A

Date of Loss:

No:

17/05/2020

Nature of Claim: TP Claim

Engine No:

SNM20D201933 No:

2ZR8238910

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLV2649H Reg No:

Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A) Reg. Date: 26/12/2017 (Man. Year: 2017)

Chassis No: ZYX102085587 Odometer: 160329 km

Colour: Metallic Blue Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

225/50 R16 Front Tyre Size: 225/50 R16 Rear Tyre Size: Front Left Side: Falken 8 mm Rear Left Side: Falken 8 mm Rear Right Side: Falken 8 mm Front Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 6,133.80 | 4,018.39 | 2,115.41 | 34.49 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,860.00 | 930.00 | 930.00 | 50.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,993.80 | 4,948.39 | 3,045.41 | 38.10 |
| Approved Total (Overridden) (S\$) | | 3,950.00 | | |
| (S\$) | 7,993.80 | 3,950.00 | 4,043.80 | 50.59 |
| + GST 7.00/7.00% (S\$) | 559.57 | 276.50 | 283.07 | 50.59 |
| Nett Amount (S\$) | 8,553.37 | 4,226.50 | 4,326.87 | 50.59 |

INSPECTION

20/05/2020 Date of Assignment:

Date Inspected: 19/05/2020 Inspected At: Hui Yang Motor Pte Ltd (HQ)

176 Sin Ming Drive #04-02, Sin Ming

AutoCare

Singapore 575721

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

| Reference | | | | | |
|--|--|--|--|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 03 Jun 2020) | | | |
| Parts: | M1-SUV | TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0) | | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | | |
| Print Code: | : (Unsubmitted, no print-code for SLV2649H) | | | | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | | |

Recommended Parts

| Qty | Part NO. | Particulars | Condition | Repairer's | Amount |
|--|---|--|--|--|---|
| 1 | | *FRONT BUMPER | Cracked | 974.45 FL | *946.50 FL |
| 1 | | *FRONT BUMPER RH SIDE RETAINER | Distorted | 133.35 FL | *133.35 FL |
| 1 | | *FRONT BUMPER RH SIDE GARNISH | Distorted | 374.45 FL | *255.00 FL |
| 20 | | *FRONT BUMPER CLIP | Necessary | 100.00 FL | *100.00 FL |
| 1 | | *FRONT BUMPER GRILLE | Distorted | 258.25 FL | *154.70 FL |
| 1 | | *FRONT BUMPER SPONGE | Cracked | 181.50 FL | *95.20 FL |
| 1 | | *FRONT BUMPER LOWER COVER | Serviceable | 182.50 FL | *- FL |
| 1 | | *FRONT BUMPER LOWER LID | Dented | 680.00 FL | *410.00 FL |
| 1 | | *FRONT CENTRE GRILLE BASE | Serviceable | 481.50 FL | *- FL |
| 1 | | *FRONT WIPER SPARE TANK | Dented | 281.50 FL | *281.50 FL |
| 1 | | *FRONT RH HEADLAMP (LED) | Cut | 2,821.40 FL | *2,327.50 FL |
| 1 | | *FRONT RH FENDER | Repair | 781.90 FL | *- FL |
| 1 | | *FRONT RH FENDER HYBRID EMBLEM | Necessary | 121.50 FL | *121.50 FL |
| 1 | | *FRONT RH FENDER PROTECTOR | Dented | 374.20 FL | *210.00 FL |
| 1 | | *FRONT RH FENDER INNER SHIELD | Cracked / Distorted | 381.90 FL | *272.60 FL |
| 10 | | *FRONT RH FENDER INNER SHIELD CLIP | Necessary | 50.00 FL | *50.00 FL |
| anchise | part. L=ListIt | emDisc. | _ | | |
| | | | Sub Total (S\$) | 8,178.40 | 5,357.85 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | | | 2,044.60 | 1,339.46 | |
| | | | Total Parts (S\$) | 6,133.80 | 4,018.39 |
| | 1 1 20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 1 1 20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 1 *FRONT BUMPER 1 *FRONT BUMPER RH SIDE RETAINER 1 *FRONT BUMPER RH SIDE GARNISH 20 *FRONT BUMPER CLIP 1 *FRONT BUMPER GRILLE 1 *FRONT BUMPER SPONGE 1 *FRONT BUMPER LOWER COVER 1 *FRONT BUMPER LOWER LID 1 *FRONT CENTRE GRILLE BASE 1 *FRONT WIPER SPARE TANK 1 *FRONT WIPER SPARE TANK 1 *FRONT RH HEADLAMP (LED) 1 *FRONT RH FENDER 1 *FRONT RH FENDER HYBRID EMBLEM 1 *FRONT RH FENDER PROTECTOR 1 *FRONT RH FENDER INNER SHIELD 10 *FRONT RH FENDER INNER SHIELD CLIP anchise part. L=ListItemDisc. | 1 *FRONT BUMPER RH SIDE RETAINER Distorted 1 *FRONT BUMPER RH SIDE GARNISH Distorted 20 *FRONT BUMPER CLIP Necessary 1 *FRONT BUMPER GRILLE Distorted 1 *FRONT BUMPER SPONGE Cracked 1 *FRONT BUMPER LOWER COVER Serviceable 1 *FRONT BUMPER LOWER LID Dented 1 *FRONT BUMPER LOWER LID Dented 1 *FRONT CENTRE GRILLE BASE Serviceable 1 *FRONT WIPER SPARE TANK Dented 1 *FRONT WIPER SPARE TANK Dented 1 *FRONT RH HEADLAMP (LED) Cut 1 *FRONT RH FENDER HYBRID EMBLEM Necessary 1 *FRONT RH FENDER HYBRID EMBLEM Dented 1 *FRONT RH FENDER INNER SHIELD Cracked / Distorted 10 *FRONT RH FENDER INNER SHIELD CIP Necessary Inchise part. L=ListIttemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$) | 1 *FRONT BUMPER Cracked 974.45 FL 1 *FRONT BUMPER RH SIDE RETAINER Distorted 133.35 FL 1 *FRONT BUMPER RH SIDE GARNISH Distorted 374.45 FL 20 *FRONT BUMPER CLIP Necessary 100.00 FL 1 *FRONT BUMPER GRILLE Distorted 258.25 FL 1 *FRONT BUMPER SPONGE Cracked 181.50 FL 1 *FRONT BUMPER LOWER COVER Serviceable 182.50 FL 1 *FRONT BUMPER LOWER LID Dented 680.00 FL 1 *FRONT BUMPER LOWER LID Dented 281.50 FL 1 *FRONT BUMPER SPARE TANK Dented 281.50 FL 1 *FRONT WIPER SPARE TANK Dented 281.50 FL 1 *FRONT RH HEADLAMP (LED) Cut 2,821.40 FL 1 *FRONT RH FENDER Repair 781.90 FL 1 *FRONT RH FENDER HYBRID EMBLEM Necessary 121.50 FL 1 *FRONT RH FENDER INNER SHIELD Cracked / Distorted 381.90 FL 10 *FRONT RH FENDER |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|----------------|-------------------------|------------|--------|
| Lab | our Items | | | |
| 1 | ALIGNMENT | New | 60.00 | 60.00 |
| 2 | TUFFKOTE | New | 100.00 | 0.00 |
| 3 | WIRING | New | 100.00 | 20.00 |
| 4 | SPRAY PAINTING | New | 800.00 | 450.00 |
| 5 | LABOUR CHARGES | New | 800.00 | 400.00 |
| | | Gross Labour Cost (S\$) | 1,860.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >