



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20005798/Aba3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 08-07-2020



ATTN:LYNN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 9046X	Veh. Inspected	GW 4261H
Policy No.	GA172837	Coverage (\$)	0.00
Claim No.	S0M02O4E	Excess (\$)	0.00
Assign From		Assign Date	18/05/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	3153
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	JN1SF4F23Z0850646	Colour	SILVER
Odometer	491818	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	WEST LAKE	6 mm
L/H Front Tyre	195 R15C	WEST LAKE	6 mm
R/H Rear Tyre	195 R15C	WEST LAKE	6 mm
L/H Rear Tyre	195 R15C	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/05/2020	Inspection Date	19/05/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------