



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

18/05/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

T? AXA.
Jasper

Accident date: 18/05/2020

Estimated repair cost for vehicle no: GW4261H NISSAN CABSTAR 3.2 03'

CHASSIS: JN1SF4F23Z0850646

S/n	Qty	Items	U/price	Amount	
				\$1,399.70	✓
1	1	Rear Tailgate <i>Dented</i>		\$20.00	10/50
2	1	Rear Tailgate 70 Km/h Sticker <i>new</i>		\$155	✓
3	1	Rear Tailgate NISSAN Sticker <i>Nec</i>		\$48.20	x
4	1	Rear R/H Tailgate Lower Side Lock <i>He nec</i>		\$150.30	✓
5	1	Rear R/H Tailgate Lower Hinge <i>Best</i>		\$135.50	x
6	1	Rear R/H Tailgate Lower Side Bracket <i>He nec</i>		\$51.60	x
7	2	Rear R/H Tailgate Lower Side Bracket Stopper Rubber <i>He nec</i>	\$25.80	\$418.80	✓
8	1	Rear Tailgate Lower Member <i>Dented</i>		\$248.60	✓
9	1	Rear R/H Tail Lamp <i>cracked</i>		\$111.20	✓
10	1	Rear R/H Tail Lamp Bracket <i>Best</i>		\$350.00	200/50
11	1	Rear Reverse Sensor <i>Damaged</i>		\$238.30	x
12	1	Rear Spare Tyre Lock <i>He nec</i>		\$550.00	x
14	1	Rear Floor Panel <i>He nec</i>			

Subtotal :- \$3,782.20

2483.60

2235.24

S/N 210

Labour charges

To remove & refit rear reverse sensor

~~\$100.00~~ 50

To remove & refit rear floor panel

~~\$300.00~~ X

To check wiring

~~\$50.00~~ 30

Tuff kote

~~\$100.00~~ 50

Towing

~~\$150.00~~ X

Panel beating

1330
~~\$1,000.00~~ 600

Spray painting

~~\$1,000.00~~ 600

Subtotal :- \$2,700.00

Total:- \$6,482.20

total: 3725.24

1/5: 3/5.

04 days

3/5

04 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: