

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AXA17008424/K1EA3Q2-1

**Date:** 26/06/2020

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	P1758221	
<b>Claimant</b>			
<b>Vehicle No :</b> SHB214U	<b>Insured Vehicle No :</b>	SLB6230K	
Date of Loss: 27/04/2017	Nature of Claim:	TP	Claim No: C0431571

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB214U		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR1450666
Reg. Date:	05/11/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U805752585
Colour:	Maroon	Odometer:	259140 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,473.54	149.40	3,324.14	95.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,481.00	790.00	1,691.00	68.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>5,954.54</b>	<b>939.40</b>	<b>5,015.14</b>	<b>84.22</b>
<b>+ Loss of Use (5.5 x S\$50.00/day) (S\$)</b>		275.00		
<b>+ Car Rental (5.5 x S\$63.67/day) (S\$)</b>		350.19		
<b>+ Doc/Search Fee (S\$)</b>		5.00		
<b>Nett Liability (S\$)</b>		<b>1,569.59</b>		

### INSPECTION

Date of Assignment:	28/04/2017		
Date Inspected:	28/04/2017 Inspected At:	SMRT Automotive Services Pte Ltd	
		(Woodlands)	
		60 Woodlands Industrial Park E4	
		Singapore 757705	
Estimated Period of Repair:	3.0 days		

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2017)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB214U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		<b>*PIXEL STICKER (SN)</b> (CONSISTENT)	Necessary	120.00 F	*120.00 F
2	1		<b>*SMRT LOGO (SN)</b> (CONSISTENT)	Necessary	7.80 F	*7.80 F
3	1		<b>*STICKER DECAL 6555 8888 (SN)</b> (CONSISTENT)	Necessary	21.60 F	*21.60 F
4	1		<b>*BUMPER REAR</b> (CONSISTENT)	Repair	458.60 F	*- F
5	1		<b>*FENDER RR/RH</b> (CONSISTENT)	Repair	766.80 F	*- F
6	1		<b>*WHEEL ,DISC</b> (CONSISTENT)	Repair	1,490.20 F	*- F
7	1		<b>*BUMPER SEAL ,RR RH</b> (CONSISTENT)	Serviceable	65.70 F	*- F
8	1		<b>*BUMPER SIDE RETAINER RR/RH</b> (CONSISTENT)	Serviceable	94.80 F	*- F
9	1		<b>*SENSOR REVERSE</b> (CONSISTENT)	Serviceable	180.00 F	*- F
10	1		<b>*FENDER LINER RR/RH</b> (CONSISTENT)	Serviceable	141.30 F	*- F
11	1		<b>*TYRE</b> (CONSISTENT)	Serviceable	126.74 F	*- F
					<b>Total Parts (S\$)</b>	<b>3,473.54 149.40</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	845.00	300.00
2	SPRAY PAINT	New	936.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
8	TO REPLACE SUNDRY PARTS	New	100.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,481.00</b>	<b>790.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >