

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20005802/NQF3E2

**Date:** 21/07/2020

### REFERENCE

Insured/Claimant: MOHAMMAD NURRAIHAN BIN RAHMAT Policy No: 2070032789  
Date of Loss: 17/05/2020 Nature of Claim: OD Claim No: 8879576741SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ8256M**  
Make & Model: YAMAHA GDR155A (AEROX), 155cc Engine No: G3J8E0108570  
Reg. Date: 23/12/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ057437  
Colour: Black Odometer: 5898 km  
Engine Capacity: 155 cc  
Market Value/New Car Price: S\$9,500.00  
Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 110/80 R14 Rear Tyre Size: 140/70 R14  
Front Left Side: IRC 4 mm Rear Left Side: IRC 4 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,201.00	2,083.50	1,117.50	34.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	520.00	1,260.00	70.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,981.00</b>	<b>2,603.50</b>	<b>2,377.50</b>	<b>47.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,100.00</b>		
<b>- Excess (\$\$)</b>	300.00	300.00	0.00	0.00
<b>(\$\$)</b>	4,681.00	1,800.00	2,881.00	61.55
<b>+ GST 7.00/7.00% (\$\$)</b>	327.67	126.00	201.67	61.55
<b>Nett Amount (\$\$)</b>	<b>5,008.67</b>	<b>1,926.00</b>	<b>3,082.67</b>	<b>61.55</b>

### INSPECTION

Date of Assignment: 19/05/2020  
Date Inspected: 20/05/2020 Inspected At: Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218216

Estimated Period of Repair: 3.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD REAR COVER	Cracked	75.00 FL	*75.00 FL
2	1		*FRONT MUDGUARD	Cracked	95.00 FL	*80.00 FL
3	1		*WHEEL AXLE	Serviceable	60.00 FL	*- FL
4	1		*BRAKE DISK	Serviceable	185.00 FL	*- FL
5	1		*RIGHT FORK ASSY	Bent	420.00 FL	*300.00 FL
6	1		*LEFT FORK ASSY	Bent	420.00 FL	*300.00 FL
7	1		*STEERING STEM	Bent	220.00 FL	*100.00 FL
8	2		*STEERING STEM BEARINGS	Necessary	90.00 FL	*90.00 FL
9	1		*CENTRE COVER INNER BODY	Deformed	120.00 FL	*120.00 FL
10	1		*CENTRE COVER LOWER	Scratched	140.00 FL	*140.00 FL
11	1		*FRONT COVER	Deformed	95.00 FL	*95.00 FL
12	1		*HEADLAMP LOWER COVER	Bent	75.00 FL	*75.00 FL
13	1		*LEFT FRONT FAIRING	Deformed	150.00 FL	*120.00 FL
14	1		*LEFT FRONT FAIRING AMBLEMS	Necessary	35.00 FL	*35.00 FL
15	1		*RIGHT FRONT FAIRING	Deformed	150.00 FL	*120.00 FL
16	1		*RIGHT FRONT FAIRING AMBLEMS	Necessary	35.00 FL	*35.00 FL
17	1		*TOP COVER FRONT	Scratched	95.00 FL	*70.00 FL
18	1		*TOP COVER FRONT AMBLEM	Necessary	20.00 FL	*20.00 FL
19	1		*FRONT SPORT RIM	Serviceable	420.00 FS	*- FS
20	1		*LEFT INNER BLACK COVER	Deformed	85.00 FL	*85.00 FL
21	1		*RIGHT INNER BLACK COVER	Deformed	85.00 FL	*85.00 FL
22	1		*HEADLAMP ASSY	Cracked	295.00 FL	*250.00 FL
23	1		*UPPER INNER COVER CENTRE	Scratched	145.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,510.00</b>	<b>2,315.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	309.00	231.50
<b>Total Parts (\$\$)</b>	<b>3,201.00</b>	<b>2,083.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	300.00
3	TO REMOVE, REPLACE AND BALANCE FRONT WHEEL RIM	New	120.00	30.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	90.00
6	SPRAY PAINTING	New	300.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,780.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >