

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20005803/FEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800049654
Claimant Vehicle No :	SHD3362U	Insured Vehicle No :	SMA2102S
Date of Loss:	17/05/2020	Nature of Claim:	TP
		Claim No:	0802352371SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3362U		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDHU728018
Reg. Date:	21/07/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU092209
Colour:	Blue	Odometer:	476418 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,065.80	1,980.12	85.68	4.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	560.00	270.00	32.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,895.80	2,540.12	355.68	12.28
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,895.80	2,000.00	895.80	30.93
+ GST 7.00/7.00% (S\$)	202.71	140.00	62.71	30.94
Nett Amount (S\$)	3,098.51	2,140.00	958.51	30.93
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	19/05/2020	
Date Inspected:	19/05/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: PARASURAM SHANMUGAM**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	2,256.40 FL	*2,256.40 FL
2	1		*RH WHEEL HUB COVER	Not Necessary	107.10 FL	*- FL
3	1		*FRONT DOOR APP LOGO	Necessary	75.00 FS	*75.00 FS
4	1		*FRONT DOOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	2,538.50 2,431.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	472.70 451.28
					Total Parts (\$\$)	2,065.80 1,980.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	280.00	240.00
2	SPRAY PAINTING CHARGE	New	400.00	200.00
3	TRANSFER DOOR PARTS	New	90.00	90.00
4	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			830.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >