

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 May 2020		21 May 2020 10:15 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: LIM SOO KHING , ID: S6814478G									
Main Claimant: Chen Yizhou									
Vehicle Reg. No.: FBH9946X		Date of Loss: 17/05/2020 00:00 - :59 [77 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D201940/C02		Policy/Cover Note No.: DMPCSN20000620000							
Vehicle Reg. No. (Insured): SBD9696M		Policy No. (Claimant): 5114913268							
		Excess: S\$0.00							
Repairer: Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/06/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBH9946X (SNM20D201940/C02)**
[SBD9696M]

TP

Chen Yizhou

May 17 2020 12:00AM

[LIM SOO KHING]

Hua Chin (2000) Trading Motor Service Centre

View

Photos/Images					
			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/06/20 17:36	General View		Load JPG	
2	02/06/20 17:36	General View		Load JPG	
3	02/06/20 17:36	General View		Load JPG	
4	02/06/20 17:36	General View		Load JPG	
5	02/06/20 17:36	General View		Load JPG	
6	02/06/20 17:36	General View		Load JPG	
7	02/06/20 17:36	General View		Load JPG	
8	02/06/20 17:36	General View		Load JPG	
9	02/06/20 17:36	General View		Load JPG	
10	02/06/20 17:36	General View		Load JPG	
11	02/06/20 17:36	General View		Load JPG	
12	02/06/20 17:36	General View		Load JPG	
13	02/06/20 17:36	General View		Load JPG	
14	02/06/20 17:36	General View		Load JPG	
15	02/06/20 17:36	General View		Load JPG	
16	02/06/20 17:36	General View		Load JPG	
17	02/06/20 17:36	General View		Load JPG	
18	02/06/20 17:36	General View		Load JPG	
19	02/06/20 17:36	General View		Load JPG	
20	02/06/20 17:36	General View		Load JPG	
21	02/06/20 17:36	General View		Load JPG	
22	02/06/20 17:36	General View		Load JPG	
23	02/06/20 17:36	General View		Load JPG	
24	02/06/20 17:36	General View		Load JPG	
25	02/06/20 17:36	General View		Load JPG	
26	02/06/20 17:36	General View		Load JPG	
27	02/06/20 17:36	General View		Load JPG	
28	02/06/20 17:36	General View		Load JPG	
29	02/06/20 17:36	General View		Load JPG	
30	02/06/20 17:36	General View		Load JPG	
31	02/06/20 17:36	General View		Load JPG	
32	02/06/20 17:36	General View		Load JPG	
33	02/06/20 17:36	General View		Load JPG	
34	02/06/20 17:36	General View		Load JPG	
35	02/06/20 17:36	General View		Load JPG	
36	02/06/20 17:36	General View		Load JPG	
37	02/06/20 17:36	General View		Load JPG	
38	02/06/20 17:36	General View		Load JPG	
39	02/06/20 17:36	General View		Load JPG	
40	02/06/20 17:36	General View		Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	02/06/20 17:36	General View		Load JPG ☒
42	02/06/20 17:36	General View		Load JPG ☒
43	02/06/20 17:36	General View		Load JPG ☒
44	02/06/20 17:36	General View		Load JPG ☒
45	02/06/20 17:36	General View		Load JPG ☒
46	02/06/20 17:36	General View		Load JPG ☒
47	02/06/20 17:36	General View		Load JPG ☒
48	02/06/20 17:36	General View		Load JPG ☒
49	02/06/20 17:36	General View		Load JPG ☒
50	02/06/20 17:36	General View		Load JPG ☒
51	02/06/20 17:36	General View		Load JPG ☒
52	02/06/20 17:36	General View		Load JPG ☒
53	02/06/20 17:36	General View		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20005813/T1QF3S2**Date:** 03/06/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN20000620000
Claimant Vehicle No :	FBH9946X	Insured Vehicle No :	SBD9696M
Date of Loss:	17/05/2020	Nature of Claim:	TP
		Claim No:	SNM20D201940/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH9946X	Engine No:	21CG028430
Make & Model:	YAMAHA FZ16, 153cc (M)	Chassis No:	ME121C0G9D2028584
Reg. Date:	29/11/2013 (Man. Year: 2013)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/05/2020	
Date Inspected:	20/05/2020 Inspected At:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING Singapore 659578
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/3/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Jun 2020)	
Parts:	N/A	YAMAHA FZ16 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH9946X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >