Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20005822/KEA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SLS7539A Insured Vehicle No: SHC2954Z

Vehicle No:

Date of Loss: 16/05/2020 Nature of Claim: ΤP Claim No: MCT20050111

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLS7539A Reg No:

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS089234

Reg. Date: 03/10/2017 (Man. Year: 2017) Chassis No: JTDKB3FUX03571024

Colour: Metallic Silver Odometer: 236031 km

Engine Capacity: 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Rear Left Side: Front Left Side: Yokohama 8 mm Yokohama 8 mm Yokohama 8 mm Front Right Side: Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
840.07	436.95	403.12	47.99
0.00	0.00	0.00	
970.00	350.00	620.00	63.92
0.00	0.00	0.00	
0.00	0.00	0.00	
1,810.07	786.95	1,023.12	56.52
126.70	55.09	71.61	56.52
1,936.77	842.04	1,094.73	56.52
+ Car Rental (2.0 x S\$62.95/day) (S\$) + Doc/Search Fee (S\$) Nett Liability (S\$)			
	840.07 0.00 970.00 0.00 0.00 1,810.07 126.70 1,936.77 62.95/day) (\$\$) Search Fee (\$\$)	840.07 436.95 0.00 0.00 970.00 350.00 0.00 0.00 0.00 0.00 1,810.07 786.95 126.70 55.09 1,936.77 842.04 62.95/day) (\$\$) 125.90 6earch Fee (\$\$) 7.45	840.07 436.95 403.12 0.00 0.00 0.00 970.00 350.00 620.00 0.00 0.00 0.00 0.00 0.00 0.00 1,810.07 786.95 1,023.12 126.70 55.09 71.61 1,936.77 842.04 1,094.73 62.95/day) (\$\$) 125.90 Gearch Fee (\$\$)

INSPECTION

Date of Assignment: 19/05/2020

Date Inspected: 19/05/2020 Inspected At: Esteem Performance Pte Ltd (HQ)

Blk 5033 Ang Mo Kio Ind Park 2, #01-

259

Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)		
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	Print Code: (Unsubmitted, no print-code for SLS7539A)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	497.50 FL	*-FL	
2	10		*REAR BUMPER CLIP	Not Necessary	40.00 FL	*-FL	
3	1		*REAR BUMPER LOWER GARNISH CENTRE	Dented	582.60 FL	*582.60 FL	
F=Fra	F=Franchise part. L=ListItemDisc.						
				Sub Total (S\$)	1,120.10	582.60	
- List Item Discount on L Items 25.00/25.00% (S\$)			280.03	145.65			
				Total Parts (S\$)	840.07	436.95	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,END PANEL)	New	400.00	150.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,END PANEL)	New	400.00	200.00
3	TO CHECK WIRING	New	50.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	0.00
	Gross Labour Cost (S\$)		970.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >