

PPRAISAL SERVI

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Automotive

Fax: 6996 6442

Business Reg. No.:

Email: dylanlee.as @gmail.com

Evaluation & Consultation

Our Reference: TP/1908/FBF1986T/SM

VEHICLE APPRAISAL REPORT

Inspection,

Mr Wan Juraimi Bin Andally Report Date:

07 Nov 2019

589D Montreal Drive #09-128

Singapore 754589

REFERENCE

Your Reference No

: Not Advised

Date of Inspection

: 22 Aug 2019

Type of Appraisal Date of Accident

: Third Party : 08 Aug 2019

Date of Re-inspection 1 Date of Re-inspection 2

: 29 Aug 2019 : 04 Nov 2019

PARTICULARS OF VEHICLE

Registration No.

: FBF1986T

First Reg Date : 14 Mar 2011

: 13 Mar 2021

Make Model Yamaha YZF-R1 COE Expiry Odometer

: Meter missing

Color

Black

Engine No.

: N519E014714

Manufacturing Year : 2011

Chassis No.

: JYARN221000010383

CONDITIONS OF VEHICLE (STATIC CHECK AT TIME OF INSPECTION ONLY)

Front Brake

: Serviceable

Steering

: Distorted

Rear Brake

: Serviceable

Modification

None

TYRE / CONDITION

Location

Make & Size

Front

Bridgestone 120/70 R17

Thread 4 mm

Rear

Bridgestone 190/50 R17

4 mm

DAMAGE PROFILE

The vehicle sustained damages on all sides.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$11,200.00 on lump sum basis

Estimated period required for repairs: (7) days

Survey conducted at: Speedy Motor Cycle Service Centre

Enclosed (64) photographs depicting damages to the vehicle

The survey was conducted on a WITHOUT PREJUDICE basis.



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220 Tel: 9101 7844 Fax: 6996 6442 Business Reg. No.:

53387981K

Email: dylanlee.as @gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference: TP/1908/FBF1986T/SM

ASSESSMENT FOR REPAIR: FBF1986T

			Repairer's	<u>Our</u>	
Qty	Description	Condition	Estimate	Assessment	
2 pes	Handle bar @224.00 X SVC	Bent	448.00	448.00 x	
2 pcs	Handle bar end assy @111.00 X SVC	Cut	222.00	222.00 X	
1 pc	Clutch lever	Cut	77.00	77.00 38	
1 pc	Brake lever X SVC	Cut	112.00	112.00 X	
1 pc	Brake light cable x svc	Broken	46.00	46.00 X	
1 pc	Reservoir tank assy	Broken	80.00	80.00 42	
2 pcs	Console panel @85.00	Missing	170.00	170.00 134	
1 pc	Meter assy	Missing	1,599.00	1,599.00 1110	
2 pcs	Mirror assy @139.00	Missing	278.00	278.00 156	
1 pc	Front screen	Missing	339.00	339.00 225	
1 pc	Front upper body	Missing	764.00	764.00 480	
1 pc	Headlight unit complete	Missing	991.00	991.00 325	
1 set	Headlight cord	Missing	243.00	243.00 185	
1 pc	Front stay	Missing	456.00	456.00 357	
1 pc	Air intake front box	Missing	101.00	101.00 🗸	
2 pcs	Air intake side box @67.00	Missing	134.00	134.00	
2 pes	Air intake duct @48.00	Missing	96.00	96.00 🗸	
2 pcs	Air intake duct grill assy @41.00	Missing	82.00	82.00 36	
1 pc	Handle bar shimmy damper assy	Cut & Distorted	1,188.00	1,188.00 🗸	
1 pc	Steering cover assy	Missing	19.00	19.00 🗸	
1 pc	Horn complete	Usable	128.00	~	
1 pc	Front fender	Broken	277.00	277.00 148	
2 pcs	Front flasher light @53.00	Cut / Broken	106.00	106.00 🗸	
2 pcs	Side top lid assy @114.00	Broken	228.00	228.00 90	
2 pcs	Side duct assy @128.00	Broken / Deformed	256.00	256.00 🗸	
2 pcs	Side panel assy @674.00	Broken	1,348.00	1,348.00 800	
2 pcs	Side inner front panel @82.00	Broken	164.00	164.00 90	
2 pcs	Side inner rear panel @109.00	LH Broken	218.00	109.00 28	
2 pcs	Under cover assy @403.00	Usable	806.00	~	
1 pc	Crankcase cover LH	Cut	248.00	248.00 🗸	
l pc	Crankcase cover gasket LH	Necessary	41.00	41.00 🗸	
1 pc	Rear footrest RH X SVC	Cut	99.00	99.00 X	
l pc	Rear footrest bracket RH X SVC	Cut	272.00	272.00 x	
1 pc	Rear cover assy x svc	Cut	555.00	555.00 x	
1 pc	Rear fender assy	Hldr Broken	286.00	286.00 210	
2 pcs	Rear flasher light assy @58.00	Usable	116.00	~	
2 pcs	Real Hasher light assy (2,50.00	Ostolo	12,593.00	11,434.00 6643	
		Less 10%	1,259.30	1,143.40	
		1.033 1070	11,333.70	10,290.60 5978.7	
			11,555.70	10,290.00 5976.7	
	Special Nett Items				
1 pc	Front number sticker	Missing	15.00	12.00 🗸	
1 set	Steering cone & bearing X SVC	Necessary / 50%	204.00	102.00 X	
1 set	Body slider	Cut	150.00	120.00 45	
1 pc	Crankcase cover protector	Cut	72.00	72.00	
ı pe	Crankouse cover protector	Cui	12.00	72.00	



1 1 1

LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Fax: 6996 6442

Business Reg. No.:

53387981K

Email: dylanlee.as @gmail.com

Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference: TP/1908/FBF1986T/SM

set pc	Swing arm slider Rear number plate	Cut Cracked	100.00 20.00	80.00 18.00	45 ✓
set	Muffler, Arrow	Dented	2,152.00	2,152.00	\checkmark
			2,698.00	2,544.00	2344
	Total Parts		14,031.70	12,834.60	
	Labour Charges				
1	Towing fee		80.00	60.00	50
2	Repair front forks, replace oil seal at	nd align steering	300.00	250.00	Χ
3	Spray painting for body covers		450.00	420.00	250
4	Workmanship to renew damaged parts		500.00	450.00	300
			1,330.00	<u>1,180.00</u>	600
	Total Parts & Labours Concluded		15,361.70	14,014.60	8922.7
	Lump Sum Repair Adjustment			11,200.00	7100

5 DAYS

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment above.

Yours faithfully, LEE APPRAISAL SERVICES

MAMION



Lee Kah Pang

Dip Mech Engr, BCompSc