Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19014855/GQF3E2-1

Date: 21/05/2020

REFERENCE

China Taiping Insurance Handling Insurer: Policy No: DMB1SN16912618022 (Singapore) Pte. Ltd.

Claimant Vehicle FBF1986T Insured Vehicle PC6030T

No: No:

Claim Date of Loss: 08/08/2019 Nature of Claim: TP SNM19D203750C02 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF1986T

Make & Model: YAMAHA YZF-R1, 998cc (M) Engine No: N519E014714

Reg. Date: 14/03/2011 (Man. Year: 2011) Chassis No: JYARN221000010383

Colour: Black Odometer: 0 km

Engine Capacity: 998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

190/50Z R17 Front Tyre Size: 120/70Z R17 Rear Tyre Size: Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm

Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,046.70	8,322.70	5,724.00	40.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	600.00	730.00	54.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,376.70	8,922.70	6,454.00	41.97
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	15,376.70	7,100.00	8,276.70	53.83

INSPECTION

Date of Assignment: 19/05/2020

Date Inspected: 23/08/2019 Inspected At: Speedy Motor Cycle Service Centre (HQ)

10 ANG MO KIO IND PARK 2A #05-21

Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 21/5/2020

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 May 2020)

Parts: N/A YAMAHA YZF-R1 998cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBF1986T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HANDLE BAR	Serviceable	448.00 FL	*- FL
2	2		*HANDLE BAR END ASSY	Serviceable	222.00 FL	*- FL
3	1		*CLUTCH LEVER	Cut	77.00 FL	*38.00 FL
4	1		*BRAKE LEVER	Serviceable	112.00 FL	*- FL
5	1		*BRAKE LIGHT CABLE	Serviceable	46.00 FL	*- FL
6	1		*RESERVOIR TANK ASSY	Broken	80.00 FL	*42.00 FL
7	2		*CONSOLE PANEL	Missing	170.00 FL	*134.00 FL
8	1		*METER ASSY	Missing	1,599.00 FL	*1,110.00 FL
9	2		*MIRROR ASSY	Missing	278.00 FL	*156.00 FL
10	1		*FRONT SCREEN	Missing	339.00 FL	*225.00 FL
11	1		*FRONT UPPER BODY	Missing	764.00 FL	*480.00 FL
12	1		*HEADLIGHT UNIT COMPLETE	Missing	991.00 FL	*325.00 FL
13	1		*SET HEADLIGHT CORD	Missing	243.00 FL	*185.00 FL
14	1		*FRONT STAY	Missing	456.00 FL	*357.00 FL
15	1		*AIR INTAKE FRONT BOX	Missing	101.00 FL	*101.00 FL
16	2		*AIR INTAKE SIDE BOX	Missing	134.00 FL	*134.00 FL
17	2		*AIR INTAKE DUCT	Missing	96.00 FL	*96.00 FL
18	2		*AIR INTAKE DUCT GRILL ASSY	Missing	82.00 FL	*36.00 FL
19	1		*HANDLE BAR SHIMMY DAMPER ASSY	Cut / Distorted	1,188.00 FL	*1,188.00 FL
20	1		*STEERING COVER ASSY	Missing	19.00 FL	*19.00 FL
21	1		*HORN COMPLETE	Usable	128.00 FL	*- FL
22	1		*FRONT FENDER	Broken	277.00 FL	*148.00 FL
23	2		*FRONT FLASHER LIGHT	Cut / Broken	106.00 FL	*106.00 FL
24	2		*SIDE TOP LID ASSY	Broken	228.00 FL	*90.00 FL
25	2		*SIDE DUCT ASSY	Broken / Deformed	256.00 FL	*256.00 FL
26	2		*SIDE PANEL ASSY	Broken	1,348.00 FL	*800.00 FL
27	2		*SIDE INNER FRONT PANEL	Broken	164.00 FL	*90.00 FL
28	2		*UNDER COVER ASSY	Usable	806.00 FL	*- FL
29	1		*CRANKCASE COVER LH	Cut	248.00 FL	*248.00 FL
30	1		*CRANKCASE COVER GASKET LH	Necessary	41.00 FL	*41.00 FL
31	1		*REAR FOOTREST BRACKET RH	Serviceable	272.00 FL	*- FL
32	1		*REAR COVER ASSY	Serviceable	555.00 FL	*-FL
33	1		*REAR FENDER ASSY	Hldr Broken	286.00 FL	*210.00 FL
34	2		*REAR FLASHER LIGHT ASSY	Usable	116.00 FL	*-FL
35	1		*REAR FOOTREST RH	Serviceable	99.00 FL	*- FL
36	1		*FRONT NUMBER STICKER	Missing	15.00 FS	*12.00 FS
37	1		*SET STEERING CONE & BEARING	Serviceable	204.00 FS	*-FS
38	1		*SET BODY SLIDER	Cut	150.00 FS	*45.00 FS
39	1		*CRANKCASE COVER PROTECTOR	Cut	72.00 FS	*72.00 FS

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET SWING ARM SLIDER	Cut	100.00 FS	*45.00 FS
41	1		*REAR NUMBER PLATE	Cracked	20.00 FS	*18.00 FS
42	1		*SET MUFFLER, ARROW	Dented	2,152.00 FS	*2,152.00 FS
43	1		*SIDE INNER REAR PANEL	N/S Broken	218.00 FL	*28.00 FL
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	15,306.00	8,987.00
- List Item Discount on L Items 10.00/10.00% (S\$)			1,259.30	664.30		
				Total Parts (S\$)	14,046.70	8,322.70
Report was unsubmitted during this print-out.						

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING FEE	New	80.00	50.00
2	REPAIR FRONT FORKS, REPLACE OIL SEAL AND ALIGN STEERING	New	300.00	0.00
3	SPRAY PAINTING FOR BODY COVERS	New	450.00	250.00
4	WORKMANSHIP TO RENEW DAMAGED PARTS	New	500.00	300.00
	Gross Labour Cost (S\$)		1,330.00	600.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >