

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20005831/KEA3Q2**Date:** 05/01/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMK3131Z	Insured Vehicle No :	SHB4325G
Date of Loss:	15/05/2020	Nature of Claim:	TP
		Claim No:	MCT20050110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3131Z		
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN EDITION E (R18 LED SR) (A)	Engine No:	27492030572019
Reg. Date:	26/04/2016 (Man. Year: 2015)	Chassis No:	WDD2120342B305630
Colour:	Metallic Light Blue	Odometer:	43841 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,085.00	15,988.70	6,096.30	27.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	2,300.00	1,860.00	44.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,245.00	18,288.70	7,956.30	30.32
+ GST 7.00/7.00% (S\$)	1,837.15	1,280.21	556.94	30.32
Nett Amount (S\$)	28,082.15	19,568.91	8,513.24	30.32
+ Car Rental (8.0 x S\$180.00/day) (S\$)		1,440.00		
Nett Liability (S\$)		21,008.91		

INSPECTION

Date of Assignment:	20/05/2020		
Date Inspected:	20/05/2020	Inspected At:	Bifrost Auto Pte Ltd (HQ) 176 Sin Ming Drive, #03-09 Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$120,000
LTA REBATE: \$77,954
NETT VALUE: \$42,046

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jun 2021)

Parts: 143 MERCEDES-BENZ E200 2.0 SEDAN EDITION E (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK3131Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,760.00 FL	*1,435.00 FL
2	1		*FRONT BUMPER SPONGE	Serviceable	149.00 FL	*- FL
3	1		*RH FRONT BUMPER INNER PART	Cracked	142.00 FL	*142.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	600.00 FL	*- FL
5	1		*FRONT BUMPER RETAINER	O/S Distorted	180.00 FL	*90.00 FL
6	2		*FRONT BUMPER SENSOR	Dented (1 PCS ONLY)	612.00 FL	*282.30 FL
7	1		*RH FRONT BUMPER FOG LAMP COVER	Dented	63.00 FL	*63.00 FL
8	1		*FRONT BUMPER LOWER CHROME -CENTRE	Serviceable	330.00 FL	*- FL
9	2		*FRONT BUMPER LOWER CHROME -SIDE	Serviceable	500.00 FL	*- FL
10	1		*FRONT GRILLE	Dented	945.00 FL	*945.00 FL
11	1		*FRONT GRILLE EMBLEM	Necessary	143.00 FL	*143.00 FL
12	2		*HEAD LAMPS	N/S Pined / O/S Broken	10,856.00 FL	*6,794.92 FL
13	1		*RH FRONT FENDER	Bent	1,119.00 FL	*1,119.00 FL
14	1		*RH FRONT FENDER UNDER-SHIELD	Distorted	218.00 FL	*218.00 FL
15	2		*FRONT FENDER EDITION E EMBLEM	Necessary	238.00 FL	*238.00 FL
16	1		*BONNET	Bent	2,600.00 FL	*2,600.00 FL
17	1		*FRONT WINDSCREEN GLASS	Pined	1,965.00 FL	*1,965.00 FL
18	1		*FRONT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*FRONT WINDSCREEN IU BRACKET	Necessary	25.00 FS	*25.00 FS
20	1		*FRONT WINDSCREEN SOLAR FILM	Necessary	600.00 FS	*250.00 FS
21	1		*FRONT CAMERA	Shorted	1,380.00 FL	*1,380.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,465.00	17,730.22
- List Item Discount on L Items 10.00/10.00% (\$)	2,380.00	1,741.52
Total Parts (\$)	22,085.00	15,988.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	500.00
2	SPRAY PAINTING CHARGE	New	1,500.00	1,100.00
3	ANTI-RUST	New	150.00	30.00
4	REPLACE FRONT WINDSCREEN GLASS	New	180.00	120.00
5	TREATMENT	New	980.00	250.00
6	REPLACE AND REPROGRAM	New	450.00	300.00
Gross Labour Cost (\$\$)			4,160.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >