

Our Job Ref No : 305399952Date : 22/05/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : RAM: SHA7871G19/05/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: EQ SMD1856R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost\$2,450.003. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : RamDate : 22/05/2020**For Official Use Only**

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|---|--------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | N | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | 7.49 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 May 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|----------------------------------|-------|-------|--------------|
| 1 | 1 | | *BONNET ASSY X(R) | 20.00 | 0.00 | *2,265.90 FL |
| 2 | 1 | | *HEAD LAMP LH scr | 20.00 | 0.00 | *1,388.00 FL |
| 3 | 1 | | *FRONT BUMPER ASSYH cna / pp | 20.00 | 0.00 | *1,052.20 FL |
| 4 | 1 | | *FRONT BUMPER SIDE LH xnn | 20.00 | 0.00 | *14.30 FL |
| 5 | 1 | | *FRONT BUMPER TOP BRACKET LH xnn | 20.00 | 0.00 | *22.40 FL |
| 6 | 1 | | *FRONT SUPPORT PANEL xnn | 20.00 | 0.00 | *907.40 FL |
| 7 | 1 | | *FRONT ADVERTISEMENT nce | 20.00 | 0.00 | *100.00 FL |

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)

5,750.20

- List Item Discount on L Items (\$\$)

1,150.04

Total Parts (\$\$)

4,600.16

ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

\$2052.16

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|---------------------------------|--|----------|-----------------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | \$560 720.00 |
| 2 | SPRAY PAINTING | New | \$400 500.00 |
| 3 | CHECH WIRING | New | \$30 50.00 |
| 4 | REMOVR/REFIX AC CONDENSER & CHARGE GAS | New | xnn 120.00 |
| 5 | TUFF KOTE | New | xnn 60.00 |
| Gross Labour Cost (\$\$) | | | 1,450.00 |

ComfortDelGro Engineering Pte Ltd/SHA7871G/19/05/2020 16:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2052.16 3012.16
990 L/S: \$2450/2
RQM(LK)
20/05/2020 1410
RavaSura@lkkauto.com
88622728
altrepairplate
L/S
3 repair jobs