

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG20005836/R1SF3E2  
**Date:** 27/05/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700089685
<b>Claimant Vehicle No :</b>	SJX7665R	<b>Insured Vehicle No :</b>	SJA8433H
Date of Loss:	17/05/2020	Nature of Claim:	TP
		Claim No:	9697254082SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJX7665R</b>	Engine No:	G4FC9U813933
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BMAU986623
Reg. Date:	10/07/2010 (Man. Year: 2010)	Odometer:	129733 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	20/05/2020	
Date Inspected:	20/05/2020	Inspected At: Victor's Garage (HQ) 5 Soon Lee Street #03-52 Pioneer Point Singapore 627607
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER RH	Necessary	0.00 F	*- F
4	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
5	1		*FRT RH FENDER	Buckled	0.00 F	*- F
6	1		*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
8	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
9	1		*FRT RH SHOCK ABSORBER	Bent	0.00 F	*- F
10	1		*TIE-ROD LINK	Bent	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**