19/05/2020 1st



Type of Claim : TP

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Vehicle No. : GBB 2981X

Our Ref:

··		Make & Model	: TOYOTA HIACE				
		Year of Manufacture	: 2008				
		Chassis No.	: JTFHT02P400033546				
Ins Company :	MS FIRST CAPITAL	Engine No.	: 1KD1874601				
Excess :		Policy No.					
Date of Accident :	15.05.2020	Time of Accident	: 13.30				
Suggested Days of Repa	air :	In-house Vehicle Ass	sessor				
Repair Estimates		Case Owner	:				
		Signature					
Parts (a) Cost / List Pric		Contact No					
Plus/Less		<u>-</u> 68485725 / 26 JOHA	ARI / TINIE				
Total of Cost /	List \$						
(b) Nett Price Item	s _\$	LKKA	Auto Consultants hence notify				
Less		the Ri • To re	epairer of the following: survey before/after spray painting				
Total of Nett Ite	em	• To di	splay damaged part(s) during resurvey sprices are subject to confirmation				
(c) Special Nett Ite	ems \$ 430	• Third	party survey is on a "Without Prejudice" basis egal modification(s) is allowed				
		Supp	ementary item(s) must be resurveyed and lect to final approval from Insurance Company				
Total Parts Cost (Apper	, <u> </u>	Acknow	wledged by Repairer				
Labour (Appendix B)	\$ 1,030	0.00 Signate	ure:				
Total Repair Cost	\$ 1,460	<u>0.00</u> 880					
The above total will be su	ubjected to 7% G.S.T.						
Name of Surveyor		Guo Qiang					
Company	•	LKK					
Survey conducted on	·	02/06/2020 at	Address Addres				
Remarks By Surveyo							
(a) The repair of this vehicle is authorized / is not authorized until further notice. (b) Recommended Days of Repair : 3 day(s) After repair photos							
	After repair priotos						
` ′		uired / Not Required	more reposit process				
(c) Resurvey	: Requ		and topon product				
` ′	: Requ	uired / Not Required	and topon product				
(c) Resurvey	: Requ	· · · · · · · · · · · · · · · · · · ·	e:				

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	: GBB2981X	Case Owner	: JOHARI
Make & Model	: TOYOTA HIACE	Year Manufacture	: 2008
Chassis No	: JTFHT02P400033546	Engine No	: 1KD1874601
Sales Order	:	Supplier	:
Order By	:	Type of Claim	:

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LONG STICKER V NEC	1				\$ 280.00	200
2	SHORT STICKER V NEC	1				\$ 150.00	80
3							280
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17	1.1.2.20						
18							
19							
20							
21							
22							
23						****	
24							
25							
26			**************************************				
27							
28				··········			
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

Labour

Vehicle No. :	GBB2981X	Case Owner	:	JOHARI	
Make & Model:	TOYOTA HIACE AUTO	Year of Manufacture	-	2008	

	Labour December 2012				
S/No	Labour Description	Esimated	Adjusted		
		Price	Price		
1	TO KNOCK & REPAIR LEFT PANEL AND AFFACTED AREA .	\$480.00	200		
2	TO PUTTY & SPRAY PAINT LEFT PANEL AND AFFACTED AREA .	\$400.00	320		
	TO FOTTI & OF TO THAT ELL FINANCE AND ALL THE PARTY.	ψ 100.00			
3	TO REMOVE / REINSTALL INNER PANEL BOARD	\$150.00	80		
3	TO REMOVE / REINSTALL INNER PAINLE BOARD	ψ100.00	600		
	A STATE OF THE STA		000		
			Lucius manus manus .		
	A PARAMETER AND A STATE OF THE				
	The state of the s				
-	A de Mandre de la constante de				
<u> </u>			A		
					
		-			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.