



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Mohamed Zaimi Bin Ismail
Contact No	Reg No/Reg Date SKS4968B*KC17P(/ 19/07/2018
	Date In/Mileage 18/05/2020/ 0
	Chassis No KNAPH816MJ5465336
	Engine No 04HBJH374072
	Make/Model KIA/SORZ.2ADDGS7
	Colour/Trim ASP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	19/05/2020/ 15:10	DS	218 / MarsLer	45437

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				100.00
S MIPNT88088 TO TRANSFER LHF AND LHR DOOR COMPONENT & MECHANISM PARTS				600.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR LHR OTR QTR PNL				1200.00
S MIPNT88088 TO REMOVE AND RE-INSTALL FUELLINING AND PIPING TO GIVE WAY FACILATATE REPAIR LHR OTR QTR PNL				600.00
S MIPNT88088 TO REPLACE LHF FENDER,LHF DOOR,LHR DOOR,ETC -TO REPAIR LHR OTR QTR PNL STRAIGHTEN,REFORM,ALIGN ON LHS ACCIDENT AFFECTED AREAS				3600.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT98088 SPRAY PAINTINGON LHS ACCIDENT AFFECTED AREAS		4530		2520.00
M KS 92101 C5 610 LH HEADLAMP ASSY	1.00	2743.00	0.00	2743.00
M KS 66311 C5 000 LH FENDER PANEL	1.00	502.00	0.00	502.00
M KS 0G032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00
M KS 86513 C5 000 LH SIDE BRACKET-FR B	1.00	17.00	0.00	17.00
M KS 86514 C5 000 RH SIDE BRACKET - FR	1.00	15.00	0.00	15.00
M KS 76003 C5 000 LH FRONT DOOR PANEL	1.00	1444.00	0.00	1444.00
M KS 77003 C5 010 LH REAR DOOR PANEL A	1.00	1290.00	0.00	1290.00
M KS 82850 C5 000 MOULDING ASSY - FRON	1.00	71.00	0.00	71.00
M KS 82210 C5 000 WEATHERSTRIP ASSY -	1.00	95.00	0.00	95.00
M KS 83850 C5 001 MOULDING ASSY - REAR	1.00	51.00	0.00	51.00
M KS 83210 C5 000 WEATHERSTRIP ASSY -	1.00	81.00	0.00	81.00
M KS 87711 C5 000 GARNISH ASSY - FENDE	1.00	88.00	0.00	88.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of repairing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address

MS First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore 068877

Contact No

Owner Name & Vehicle Info

Cust No/Name /Mr Mohamad Zaini Bin Ismail
Reg No/Reg Date SKS4968B*KC1/ 19/07/2018
Date In/Mileage 18/05/2020/ 0
Chassis No KNAPH81BMJ5465336
Engine No D4HBJH374072
Make/Model KIA/SOR2.2ADDGS7
Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	19/05/2020/ 15:10	DS	218 / MarsLer	45437

Description of Goods / Services

			Qty	Unit Price	Disc%	Amount
M	KS 87741 C5 000	GARNISH ASSY-QTR SID	1.00	49.00	0.00	49.00
M	KS 87721 C5 200	GARNISH ASSY - FRONT	1.00	204.00	0.00	204.00
M	KS 87731 C5 200	GARNISH ASSY-RR DR S	1.00	242.00	0.00	242.00
M	KS 87539 C5 000	FILM-RR DR ANTI CHIP	1.00	10.00	0.00	10.00
M	KS 69510 C5 000	DOOR ASSY - FUEL FIL	1.00	73.00	0.00	73.00

Z NOTES

ACCIDENT ON 07/01/2020 ALONG PIE TOWARDS CHANGI
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # SHC898R TP INS : MS FIRST CAPITAL

total:8290

3760

Estimate

Lower Bumper Cover - sur.

5 Days.

before paint photos.

Guo Qiang@lkkauto.com

Guo Qiang - 82880782.

22/5/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Parts	6,995.00
Labour	0.00
Standard Menu	0.00
Specialist Job	9,070.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	16,065.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	/Mr Mohamad Zaini Bin Ismail
	Reg No/Reg Date	SKS4968B*KC17P(/ 19/07/2018
	Date In/Mileage	18/05/2020/ 0
	Chassis No	KNAPH81BMJ5465336
	Engine No	D4HBJH374072
	Make/Model	KIA/SOR2.2ADDGS7
	Colour/Trim	ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	22/05/2020/ 11:12	DS	218 / MarsLer	45437

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 86585 C5 500 LH LWR FRONT BUMPER ✓ SCR	1.00	89.00	0.00	89.00
Z NOTES SUPPLEMENTARY ITEM				
<div style="font-size: 100px; opacity: 0.3;">Estimate</div>				

Confirm & accepted by

Authorized signatory and company stamp

Parts	89.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	89.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	/Mr Mohamad Zaini Bin Ismail
	Reg No/Reg Date	SKS4968B*KC17P(/ 19/07/2018
	Date In/Mileage	08/06/2020/ 49775
	Chassis No	KNAPH81BMJ5465336
	Engine No	D4HBJH374072
	Make/Model	KIA/SOR2.2ADDGS7
	Colour/Trim	ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000034	Credit	12/06/2020/ 16:46	DS	218 / MarsLer	45437			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
S	MIPNT88088							250.00
	DIAGNOSTIC / SCANNING							
S	MIPNT88088							80.00
	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS							
S	MIPNT88088							300.00
	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR LHR OTR QTR PNL							
S	MIPNT88088							1800.00
	TO REPLACE LHF FENDER,FRONT LOWER BUMPER COVER,ETC -TO REPAIR LHF&LHR DOOR PANLE AND LHR OTR QTR PNL STRAIGHTEN,REFORM,ALIGN ON LHS ACCIDENT AFFECTED AREAS							
S	MIPNT98088							2100.00
	SPRAY PAINTINGON LHS ACCIDENT AFFECTED AREAS							
X	KS 92101 C5 610	LH HEADLAMP ASSY	1.00	2743.00	0.00	2743.00		
X	KS 66311 C5 000	LH FENDER PANEL	1.00	502.00	0.00	502.00		
X	KS 0G032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00		
X	KS 86513 C5 000	LH SIDE BRACKET-FR B	1.00	17.00	0.00	17.00		
X	KS 87711 C5 000	GARNISH ASSY - FENDE	1.00	88.00	0.00	88.00		
X	KS 87741 C5 000	GARNISH ASSY-QTR SID	1.00	49.00	0.00	49.00		
X	KS 87731 C5 200	GARNISH ASSY-RR DR S	1.00	242.00	0.00	242.00		
X	KS 87539 C5 000	FILM-RR DR ANTI CHIP	1.00	10.00	0.00	10.00		
X	KS 86585 C5 500	LH LWR FRONT BUMPER	1.00	89.00	0.00	89.00		
Z	NOTES							
	ACCIDENT ON 07/01/2020 ALONG PIE TOWARDS CHANGI							
	OWNER CLAIMING THIRD PARTY							
	REQUIRED REPLACEMENT CAR (CHAN'S)							
	TP # SHC898R TP INS : MS FIRST CAPITAL							

Confirm & accepted by

Parts	3,760.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,530.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	8,290.00

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.