

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005862/BEA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700023724

Claimant
Vehicle No : SJU6724B

Insured Vehicle No : SJJ7117E

Date of Loss: 19/05/2020

Nature of Claim: TP

Claim No: 9229674865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU6724B**

Make & Model: TOYOTA LEXUS, 2.5 IS250 (A)

Engine No: 4GR0168856

Reg. Date: 17/04/2006 (Man. Year: 2006)

Chassis No: JTHBK262302011455

Colour: Grey

Odometer: 0 km

Engine Capacity: 2500 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Goodyear 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,167.58	4,606.20	5,561.38	54.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,180.00	2,470.00	53.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,817.58	6,786.20	8,031.38	54.20
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	14,817.58	5,400.00	9,417.58	63.56
+ GST 7.00/7.00% (S\$)	1,037.23	378.00	659.23	63.56
Nett Amount (S\$)	15,854.81	5,778.00	10,076.81	63.56
+ Car Rental (7.0 x S\$160.00/day) (S\$)		1,120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,905.45		

INSPECTION

Date of Assignment: 21/05/2020

Date Inspected: 21/05/2020 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,242.30 FL	*978.00 FL
2	1		*FRONT DOOR LOCK ASSY	Not Damaged	328.40 FL	*- FL
3	1		*FRONT DOOR LOCK STRIKER	Not Damaged	84.20 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE W/SENSOR	Not Damaged	412.60 FL	*- FL
5	1		*FRONT DOOR WEATHER STRIP	Not Damaged	241.30 FL	*- FL
6	1		*FRONT DOOR TRIMBOARD	Not Damaged	423.60 FL	*- FL
7	1		*FRONT DOOR FRAME RUBBER	Not Damaged	108.50 FL	*- FL
8	1		*REAR DOOR RH	Dented	1,182.40 FL	*1,182.40 FL
9	1		*REAR DOOR WEATHERSTRIP	Not Damaged	210.30 FL	*- FL
10	1		*REAR DOOR LOCK ASSY	Not Damaged	314.50 FL	*- FL
11	1		*REAR DOOR LOCK STRIKER	Not Damaged	84.20 FL	*- FL
12	1		*REAR DOOR TRIMBOARD	Not Damaged	418.30 FL	*- FL
13	1		*REAR DOOR FRAME RUBBER	Not Damaged	108.50 FL	*- FL
14	2		*REAR SHOCK ABSORBER	Not Damaged	354.00 FL	*- FL
15	1		*REAR LOWER ARM (2 PCS)	Dented (1 PCS ONLY)	315.60 FL	*249.85 FL
16	2		*REAR UPPER ARM	Not Damaged	289.40 FL	*- FL
17	2		*REAR KNUCKLE ARM	Not Damaged	452.80 FL	*- FL
18	2		*REAR KNUCKLE ARM BEARING	Jammed (1 PCS ONLY)	187.20 FL	*187.20 FL
19	1		*REAR FENDER	Dented	1,085.30 FL	*1,045.00 FL
20	1		*REAR FENDER INNER COWLING	Not Damaged	185.60 FL	*- FL
21	1		*REAR BUMPER	Cut	1,147.60 FL	*890.00 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	209.60 FL	*130.00 FL
23	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
24	1		*FRONT DOOR SEALANT	Necessary	80.00 FS	*30.00 FS
25	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*30.00 FS
27	1		*REAR FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR DOOR SEALANT	Necessary	80.00 FS	*30.00 FS
29	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*ALLOY RIM (LOCAL REPAIR)	Cut	850.00 FS	*200.00 FS
32	1		*TYRE	Not Damaged	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,106.20 5,072.45
- List Item Discount on L Items 10.00/10.00% (\$\$) 938.62 466.25

Total Parts (\$\$) 10,167.58 4,606.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT DOOR COMPONENT	New	120.00	60.00
2	R&R REAR DOOR COMPONENT	New	120.00	60.00
3	R&R FRONT UNDERCARRIAGE PARTS	New	150.00	80.00
4	R&R FRONT TYRE AND BALANCING	New	120.00	30.00
5	WHEEL ALIGNMENT	New	120.00	60.00
6	UPHOLSTERY	New	200.00	0.00
7	CHECK WIRING	New	120.00	60.00
8	PANEL BEAT	New	1,800.00	800.00
9	SPRAY PAINT	New	1,800.00	1,000.00
10	RUST RPOOFING	New	100.00	30.00
Gross Labour Cost (\$\$)			4,650.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >