



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20005864/Eba3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 10-11-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 2921R	Veh. Inspected	SMT 3229D
Policy No.	GA442925	Coverage (\$)	0.00
Claim No.	S0M02O96	Excess (\$)	0.00
Assign From		Assign Date	21/05/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GK33418676	Colour	BLUE
Odometer	2768	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	4 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	4 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	4 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/05/2020	Inspection Date	21/05/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------