

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20005865/DEA3Q2

**Date:** 04/02/2021

### REFERENCE

|                                                         |                             |                       |
|---------------------------------------------------------|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015              |
| <b>Claimant</b>                                         |                             |                       |
| <b>Vehicle No :</b> SH9639G                             | <b>Insured Vehicle No :</b> | SHB4325G              |
| Date of Loss: 15/05/2020                                | Nature of Claim: TP         | Claim No: MCT20050110 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                                |             |                   |
|-----------------------------|------------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SH9639G</b>                                 |             |                   |
| Make & Model:               | HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) | Engine No:  | D4FDGU690492      |
| Reg. Date:                  | 24/11/2016 (Man. Year: 2016)                   | Chassis No: | KMHLB41UMHU096527 |
| Colour:                     | Blue                                           | Odometer:   | 0 km              |
| Engine Capacity:            | 1685 cc                                        |             |                   |
| Market Value/New Car Price: | N/A                                            |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>              |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/60 R16   | Rear Tyre Size:  | 205/60 R16   |
| Front Left Side:  | Hankook 5 mm | Rear Left Side:  | Hankook 5 mm |
| Front Right Side: | Hankook 5 mm | Rear Right Side: | Hankook 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 38,530.80         | 30,436.36         | 8,094.44          | 21.01         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 5,420.00          | 3,040.00          | 2,380.00          | 43.91         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>43,950.80</b>  | <b>33,476.36</b>  | <b>10,474.44</b>  | <b>23.83</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>16,200.00</b>  |                   |               |
| <b>(S\$)</b>                                     | 43,950.80         | 16,200.00         | 27,750.80         | 63.14         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 3,076.56          | 1,134.00          | 1,942.56          | 63.14         |
| <b>Nett Amount (S\$)</b>                         | <b>47,027.36</b>  | <b>17,334.00</b>  | <b>29,693.36</b>  | <b>63.14</b>  |
| <b>+ Loss of Use (14.0 x S\$40.00/day) (S\$)</b> |                   | 560.00            |                   |               |
| <b>+ Car Rental (14.0 x S\$112.67/day) (S\$)</b> |                   | 1,577.38          |                   |               |
| <b>+ Other Costs (S\$)</b>                       |                   | 80.00             |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>19,551.38</b>  |                   |               |

### INSPECTION

Date of Assignment: 21/05/2020

Date Inspected: 21/05/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)  
Blk 9 Sector C, #01-42 Sin Ming  
Industrial Estate  
Singapore 575644

Estimated Period of Repair: 10.0 days

---

**Adjuster:** BRYAN TANI

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                                 |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 01 Dec 2020)                                   |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                               |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SH9639G)                                                                                                                                     |                                                                                 |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                 |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                 |

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition          | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|--------------------|-------------|--------------|
| 1   | 1   |          | *BONNET                                  | Dented             | 2,265.90 FL | *2,265.90 FL |
| 2   | 1   |          | *BONNET RUBBER (LH)                      | Serviceable        | 35.70 FL    | *- FL        |
| 3   | 1   |          | *BONNET RUBBER (RH)                      | Serviceable        | 35.70 FL    | *- FL        |
| 4   | 2   |          | *BONNET HINGE (LH/RH)                    | Bent               | 253.40 FL   | *253.40 FL   |
| 5   | 1   |          | *BONNET LOCK                             | Bent               | 142.40 FL   | *142.40 FL   |
| 6   | 1   |          | *BONNET ABSORBER (LH ONLY)               | Serviceable        | 61.60 FL    | *- FL        |
| 7   | 1   |          | *BONNET INSULATOR                        | Bent / Crumpled    | 202.50 FL   | *202.50 FL   |
| 8   | 1   |          | *BONNET SEAL                             | Not Necessary      | 31.90 FL    | *- FL        |
| 9   | 1   |          | *BONNET INSULATOR CLIPS                  | Necessary          | 15.00 FL    | *15.00 FL    |
| 10  | 1   |          | *BONNET CABLE                            | Serviceable        | 69.60 FL    | *- FL        |
| 11  | 1   |          | *RADIATOR GRILLE H EMBLEM                | Necessary          | 129.50 FL   | *39.50 FL    |
| 12  | 1   |          | *RADIATOR GRILLE                         | Broken             | 1,480.00 FL | *1,480.00 FL |
| 13  | 1   |          | *FRONT BUMPER COVER                      | Broken             | 1,052.20 FL | *1,052.20 FL |
| 14  | 1   |          | *FRONT BUMPER SPONGE                     | Dislodged          | 379.20 FL   | *379.20 FL   |
| 15  | 1   |          | *FRONT BUMPER REINFORCEMENT              | Broken             | 588.40 FL   | *588.40 FL   |
| 16  | 2   |          | *FRONT BUMPER GRILLE (LH/RH)             | Dislodged          | 298.40 FL   | *298.40 FL   |
| 17  | 1   |          | *FRONT BUMPER LIP                        | Dislodged          | 152.00 FL   | *152.00 FL   |
| 18  | 2   |          | *FRONT BUMPER BRACKET TOP (LH/RH)        | Not Necessary      | 89.60 FL    | *- FL        |
| 19  | 2   |          | *FRONT BUMPER BRACKET (LH/RH)            | Broken             | 98.40 FL    | *98.40 FL    |
| 20  | 1   |          | *FRONT BUMPER RETAINER MOUNTING          | Not Necessary      | 76.20 FL    | *- FL        |
| 21  | 2   |          | *FRONT BUMPER GRILLE AIR DUCT (LH/RH)    | Dislodged          | 252.40 FL   | *252.40 FL   |
| 22  | 1   |          | *WIPER CONTAINER ASSY                    | Broken             | 281.60 FL   | *281.60 FL   |
| 23  | 1   |          | *HEADLAMP SUPPORT PANEL ASSY             | Broken / Dented    | 907.40 FL   | *907.40 FL   |
| 24  | 2   |          | *HEADLAMP (LH/RH)                        | Dislodged / Broken | 5,552.00 FL | *2,776.00 FL |
| 25  | 1   |          | *HEADLAMP SUPPORT TOP COVER              | Broken             | 222.60 FL   | *222.60 FL   |
| 26  | 1   |          | *RADIATOR                                | Punctured          | 1,637.20 FL | *708.50 FL   |
| 27  | 2   |          | *RADIATOR GUARD (LH/RH)                  | Broken             | 153.00 FL   | *153.00 FL   |
| 28  | 1   |          | *COOLANT                                 | Serviceable        | 45.00 FL    | *- FL        |
| 29  | 1   |          | *RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY | Broken             | 1,194.20 FL | *792.95 FL   |
| 30  | 1   |          | *RADIATOR HOSE UPPER                     | Deformed           | 229.50 FL   | *229.50 FL   |
| 31  | 1   |          | *RADIATOR HOSE LOWER                     | Not Necessary      | 135.60 FL   | *- FL        |
| 32  | 1   |          | *RADIATOR EXPANSION TANK                 | Cracked            | 163.80 FL   | *163.80 FL   |
| 33  | 2   |          | *HORN UNIT (LH/RH)                       | Broken             | 144.60 FL   | *144.60 FL   |
| 34  | 1   |          | *HORN WIRE                               | Socket Broken      | 156.60 FL   | *156.60 FL   |
| 35  | 1   |          | *AIR DUCT                                | Cut / Broken       | 171.70 FL   | *171.70 FL   |
| 36  | 1   |          | *RESONATOR TANK HOSE                     | Not Necessary      | 218.30 FL   | *- FL        |
| 37  | 1   |          | *RESONATOR TANK                          | Not Necessary      | 288.50 FL   | *- FL        |
| 38  | 2   |          | *FRONT FENDER (LH/RH)                    | Dented / Buckled   | 1,132.60 FL | *1,132.60 FL |
| 39  | 2   |          | *FRONT FENDER SHIELD (LH/RH)             | Dislodged / Torn   | 349.80 FL   | *349.80 FL   |
| 40  | 1   |          | *AIRCON CONDENSER                        | Punctured          | 947.80 FL   | *947.80 FL   |
| 41  | 1   |          | *AIRCON SUCTION & LIQUID HOSE            | Bent               | 549.10 FL   | *549.10 FL   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                         | Condition        | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------|------------------|-------------|--------------|
| 42  | 1   |          | *FRONT WINDSCREEN GLASS             | Cracked          | 882.70 FL   | *882.70 FL   |
| 43  | 1   |          | *FRONT WINDSCREEN MOULDING          | Necessary        | 133.70 FL   | *133.70 FL   |
| 44  | 1   |          | *INTER COOLER                       | Punctured / Bent | 1,032.50 FL | *1,032.50 FL |
| 45  | 1   |          | *HOSE B INTER COOLER                | Not Necessary    | 229.70 FL   | *- FL        |
| 46  | 1   |          | *HOSE B INTER COOLER INLET          | Not Necessary    | 294.50 FL   | *- FL        |
| 47  | 1   |          | *WIRING -ENGINE W/FUSE BOX          | Socket Broken    | 3,326.00 FL | *3,326.00 FL |
| 48  | 1   |          | *AIR BAG COMPLETE DRIER             | Activated        | 2,348.50 FL | *2,348.50 FL |
| 49  | 1   |          | *AIR BAG CONTROL MODULE             | Activated        | 1,894.00 FL | *1,894.00 FL |
| 50  | 1   |          | *STEERING ANGLE ASSY                | Not Necessary    | 1,150.60 FL | *- FL        |
| 51  | 1   |          | *SENSOR ASSY IMPACT -FRONT IMPACT   | Not Necessary    | 1,180.50 FL | *- FL        |
| 52  | 2   |          | *AIR BAG SENSOR                     | Activated        | 2,320.00 FL | *1,160.00 FL |
| 53  | 1   |          | *FRONT NUMBER PLATE }               | Dislodged        | 25.00 FS    | *45.00 FS    |
| 54  | 1   |          | *FRONT NO PLATE TRIM COVER }        | Dislodged        | 30.00 FS    | *- FS        |
| 55  | 1   |          | *FRONT WINDSCREEN SEALANT           | Necessary        | 45.00 FS    | *45.00 FS    |
| 56  | 1   |          | *FRONT ERP STICKER                  | Necessary        | 26.00 FS    | *26.00 FS    |
| 57  | 1   |          | *DEVICE ASSY -SWIRL                 | Broken           | 1,367.20 FL | *814.60 FL   |
| 58  | 1   |          | *AIR CLEANER BOTTOM ASSY            | Broken           | 325.00 FL   | *325.00 FL   |
| 59  | 1   |          | *FRONT FENDER APRON PANEL (RH)      | Dented           | 637.00 FL   | *637.00 FL   |
| 60  | 1   |          | *AIRCON DISCHARGE HOSE              | Bent             | 194.40 FL   | *194.40 FL   |
| 61  | 2   |          | *FRONT SAFETY BELT ASSY (LH/RH)     | Activated        | 954.40 FL   | *954.40 FL   |
| 62  | 1   |          | *FRONT WINDSCREEN PILLAR OUTER (RH) | Dented           | 1,535.90 FL | *1,535.90 FL |
| 63  | 1   |          | *WIPER PANEL TOP GARNISH            | Broken           | 476.60 FL   | *222.60 FL   |
| 64  | 1   |          | *FRONT CHASSIS MEMBER (RH)          | Dented / Bent    | 1,060.70 FL | *1,060.70 FL |
| 65  | 1   |          | *ENGINE UNDER COVER                 | Torn             | 334.60 FL   | *334.60 FL   |
| 66  | 1   |          | *STARTER MOTOR ASSY                 | Socket Broken    | 950.00 FL   | *950.00 FL   |
| 67  | 1   |          | *WIRING -ECM                        | Socket Broken    | 3,186.60 FL | *3,186.60 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>48,132.00</b> | <b>38,016.45</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 9,601.20         | 7,580.09         |
| <b>Total Parts (\$\$)</b>                                  | <b>38,530.80</b> | <b>30,436.36</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                          | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                      |          |                 |                 |
| 1                               | PANEL BEATING                                        | New      | 1,400.00        | 1,200.00        |
| 2                               | SPRAY PAINTING CHARGE                                | New      | 1,200.00        | 900.00          |
| 3                               | WIRING CHARGE                                        | New      | 100.00          | 30.00           |
| 4                               | TUFF KOTE                                            | New      | 100.00          | 40.00           |
| 5                               | TOWING CHARGE                                        | New      | 80.00           | 0.00            |
| 6                               | REMOVE/REFIX RADIATOR                                | New      | 90.00           | 50.00           |
| 7                               | REMOVE/REFIX AIRCON & REFILL GAS                     | New      | 130.00          | 80.00           |
| 8                               | REMOVE/REFIX FUSE BOX                                | New      | 120.00          | 50.00           |
| 9                               | REMOVE/REFIX FRONT WINDSCREEN GLASS                  | New      | 120.00          | 80.00           |
| 10                              | REMOVE/REFIX DASHBOARD                               | New      | 350.00          | 180.00          |
| 11                              | REMOVE/REFIX AIR BAG /STEERING WHEEL/DASHBOARD /SEAT | New      | 550.00          | 250.00          |
| 12                              | REPAIR EXHAUST PIPE                                  | New      | 80.00           | 0.00            |
| 13                              | REPAIR FRONT CUSHION SEAT (NPA)                      | New      | 0.00            | 0.00            |
| 14                              | REPAIR GEAR BOX (NPA)                                | New      | 0.00            | 0.00            |
| 15                              | REPAIR REAR TOP /LOWER CUSHION SEAT (NPA)            | New      | 0.00            | -               |
| 16                              | RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM }           | New      | 550.00          | 180.00          |
| 17                              | DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }         | New      | 550.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                      |          | <b>5,420.00</b> | <b>3,040.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >