



Your Ref : SNM20D201958/SGS2212J/TANGHL2

Date: 22nd May 2020

Our Ref : CS/CTI20005866/Kqf3e2

M/s Chine Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGS 2212J
ACCIDENT ON 20/05/2020**

Instruction was received to inspect the vehicle Reg. No. SGS 2212J. The inspection was conducted on 21/05/2020 at the premises of M/s Cheng Hoe Motor Service, 10 Ang Mo Kio Ind Park 2A, #01-04 Ang Mo Kio Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SGS 2212J
Make/Model	: Honda CRV 2.0L AT
Year of Registration	: 2007
Body Colour	: Metallic Grey
Chassis Number	: JHLRE28307C200982
Engine Capacity	: 1997 cc

The vehicle sustained damages at the front portion and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 16,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 9,011.00)
Nett Liability	<u>S\$ 6,989.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.