

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20005866/KQF3

Date: 22/05/2020

REFERENCE

Insured/Claimant: TRANSPAK
SINGAPORE PTE LTD Policy No: DMPCSNA00012982000

Date of Loss: 20/05/2020 Nature of Claim: OD Claim No: SNM20D201958/SGS2212J/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGS2212J**
Make & Model: HONDA CR-V, 2.0 L (A) Engine No: R20A11700914
Reg. Date: 07/03/2007 (Man. Year: 2006) Chassis No: JHLRE28307C200982
Colour: Metallic Grey Odometer: 0 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$16,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	100.00	0.00	100.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	100.00	0.00	100.00	100.00
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	-400.00	-500.00	100.00	-25.00

INSPECTION

Date of Assignment: 21/05/2020

Date Inspected: 21/05/2020 Inspected At:

CHENG HOE MOTOR SERVICE
10 ANG MO KIO IND PARK 2A
#01-04 ANG MO KIO AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$16,000.00
OMV : \$24,517.00
PARF Rebate (1) : \$ 0.00
Quota Premium Paid : \$25,174.00
COE Rebate (2) : \$ 9,011.00
Total Rebate (1) + (2) = : \$ 9,011.00

The total amount incurred will be Market Value \$16,000.00 minus Total Rebate \$9,011.00 = \$6,989.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 May 2020)

Parts: M1-SUV HONDA CR-V 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGS2212J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING (BY KING DOLLY)	New	100.00	0.00
Gross Labour Cost (S\$)			100.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >