

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005877/T1TF3E2

Date: 24/06/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00000561900
Claimant Vehicle No :	SLZ1101G	Insured Vehicle No :	SMP320M
Date of Loss:	20/05/2020	Nature of Claim:	TP
		Claim No:	SNM20D201965/C02/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ1101G</b>	Engine No:	CHH257039
Make & Model:	VOLKSWAGEN GOLF, 1.4 GT (A)	Chassis No:	WVWZZZAUZJW185879
Reg. Date:	13/03/2018 (Man. Year: 2018)	Odometer:	26280 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,462.19	2,204.94	257.25	10.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	4,040.00	2,480.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,982.19</b>	<b>6,244.94</b>	<b>2,737.25</b>	<b>30.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>628.75</b>	<b>437.15</b>	<b>191.60</b>	<b>30.47</b>
<b>Nett Amount (S\$)</b>	<b>9,610.94</b>	<b>6,682.09</b>	<b>2,928.85</b>	<b>30.47</b>

### INSPECTION

Date of Assignment:	21/05/2020	
Date Inspected:	03/06/2020	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2020)
<b>Parts:</b>	144	VOLKSWAGEN GOLF 1.4 GT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ1101G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,199.99 FS	*1,199.99 FS
2	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	20.38 FS	* - FS
3	1		*SUPPORT PART BUMPER INNER BRACKET RH	Not Necessary	53.29 FS	* - FS
4	1		*RETAINER FOR SPOILER SATI	Not Necessary	183.58 FS	* - FS
5	1		*SENSOR BRACKET	Necessary	12.48 FS	*12.48 FS
6	1		*SENSOR BRACKET	Necessary	12.48 FS	*12.48 FS
7	2		*SENSOR BRACKET	Necessary	23.80 FS	*23.80 FS
8	1		*SENSOR BRACKET	Necessary	12.60 FS	*12.60 FS
9	1		*SENSOR BRACKET	Necessary	12.60 FS	*12.60 FS
10	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
11	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
12	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE	Cut	89.21 FS	*89.21 FS
13	1		*FENDER RH	Bent	589.90 FS	*589.90 FS
14	1		*CROSS SUPPORT FENDER BRACKET RH	Necessary	30.84 FS	*30.84 FS
15	2		*RIVETTED CAP NUT	Necessary	2.28 FS	*2.28 FS
16	1		*EMBLEM FENDER EMBLEM - GTI	Necessary	83.42 FS	*83.42 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 2,462.19 2,204.94**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINT	New	2,400.00	1,600.00
<b>Gross Labour Cost (S\$)</b>			<b>6,520.00</b>	<b>4,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >