



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2004299  
INV Date 03/06/2020  
Reference CS/AGI20005881/Kyf3q2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 5954D

Insured Veh. SJS 4796S

Claim No. C10006338

Policy No.

Accident Date 21/05/2020

Inspection Date 22/05/2020

Description	Total
Survey Inspection	450.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005881/Kyf3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 03-06-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJS 4796S	<b>Veh. Inspected</b>	SHC 5954D
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10006338	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	STANLEY LAI	<b>Assign Date</b>	21/05/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	RENAULT LATITUDE (A)	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	VF1ABL15AUC281471	<b>Colour</b>	METALLIC WHITE / RED
<b>Odometer</b>	556111	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/60 R16	SAILUN	8 mm
<b>L/H Front Tyre</b>	215/60 R16	SAILUN	8 mm
<b>R/H Rear Tyre</b>	215/60 R16	SAILUN	9 mm
<b>L/H Rear Tyre</b>	215/60 R16	SAILUN	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	21/05/2020	<b>Inspection Date</b>	22/05/2020
<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5954D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER FRT	SERVICEABLE	747.20	-
1	BUMPER SPOILER FRT	SERVICEABLE	344.70	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	101.40	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	292.50	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	147.00	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	HEADLAMP RH	SERVICEABLE	743.60	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	128.30	-
1	FENDER PANEL FRT RH	BENT	437.10	437.10
1	WHEELARCH FRT RH	SERVICEABLE	191.40	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	11.80	-
1	FENDER BRACKET/GRILL WING HOLDER RH	SERVICEABLE	80.70	-
1	FENDER BRACKET FRT RH	SERVICEABLE	106.40	-
1	FENDER INSULATOR RH	SERVICEABLE	66.30	-
1	RADIATOR GRILLE	SERVICEABLE	969.90	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	592.70	-
1	BONNET	TO REPAIR SEE LABOUR	1,312.70	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	82.60	-
1	WIPER RESERVOIR	SERVICEABLE	179.60	-
1	WIPER RESERVOIR NECK	SERVICEABLE	29.30	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR SEAL FRT RH	SERVICEABLE	72.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-

Report Ref No. CS/AGI20005881/Kyf3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR SEAL LOWER FRT RH	SERVICEABLE	91.17	-
1	DOOR FINISHER FRT RH	SERVICEABLE	515.06	-
1	DOOR FINISHER CLIP KIT FRT RH	SERVICEABLE	94.00	-
1	DOOR REGULATOR FRT RH	SERVICEABLE	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR MOULDING FRT RH	SERVICEABLE	291.27	-
1	DOOR HARNESS WIRE FRT RH	SERVICEABLE	2,670.00	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
	LESS 10% DISCOUNT		-2,022.40	-328.18
			18,201.55	2,953.58
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	68.00	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	25.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	20.00	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	25.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	38.00	-
1	FRONT RENAULT TYRE (SN)	SERVICEABLE	300.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	100.00	-
1	FRONT RENAULT TYRE RIM (SN)	NOT NECESSARY	380.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	55.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	28.00	-
			1,368.00	75.00

Report Ref No. CS/AGI20005881/Kyf3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,500.00	660.00
	TO PULL AND JACK OUT BODY FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT RH,BONNET,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH AND ROCKER PANEL OUTER RH.		6,500.00	500.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	-		-	-
	-		-	-
	-		-	-
			15,550.00	1,300.00
	<b>GRAND TOTAL</b>		<b>35,119.55</b>	<b>4,328.58</b>

Report Ref No. CS/AGI20005881/Kyf3q2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,450.00</b>
---	--	--	-----------------

Report Ref No. CS/AGI20005881/Kyf3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 5954D

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



