

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG14023471/KEA3Q2-1

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100392402

Claimant
Vehicle No : SJP7452E **Insured Vehicle No :** SGG5290B

Date of Loss: 05/12/2014 Nature of Claim: TP Claim No: 2128788524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7452E	Engine No:	HIDDEN
Make & Model:	SUBARU WRX, 2.5 (M)	Chassis No:	JF1GDBKH35G055544
Reg. Date:	01/11/2005 (Man. Year: 2005)	Odometer:	126842 km
Colour:	Black		
Engine Capacity:	1994 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Archilles 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Archilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,576.56	1,304.96	271.60	17.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	750.00	100.00	11.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,426.56	2,054.96	371.60	15.31
Approved Total (Overridden) (\$\$)		1,600.00		
(\$\$)	2,426.56	1,600.00	826.56	34.06
+ GST 7.00/7.00% (\$\$)	169.86	112.00	57.86	34.06
Nett Amount (\$\$)	2,596.42	1,712.00	884.42	34.06
+ Loss of Use (4.0 x S\$80.00/day) (\$\$)		320.00		
(\$\$)		2,032.00		
Liabe Amount (50.00%) (\$\$)		1,016.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,018.00		
Global Sum Settlement (\$\$)		1,020.00		

INSPECTION

Date of Assignment: 09/12/2014

Date Inspected: 09/12/2014 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-

76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Cracked	760.10 FL	*760.10 FL
2	1		*REAR O/S BUMPER SIDE RETAINER	Distorted	62.00 FL	*62.00 FL
3	1		*REAR O/S TAILLAMP	Cut	496.60 FL	*496.60 FL
4	1		*REAR BOOT COMPARTMENT SPARE TANK	Serviceable	152.00 FL	*- FL
5	1		*REAR BUMPER LAMINATION STICKER	Necessary	400.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,870.70	1,568.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	294.14	263.74
Total Parts (\$\$)	1,576.56	1,304.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REAR BUMPER & END PANEL LOWER	New	450.00	400.00
2	TO PANEL BEATING DAMAGED PARTS ,REMOVE & RENEW REAR BUMPER,ALIGN & ADJUST REPLACED PARTS	New	400.00	350.00
Gross Labour Cost (\$\$)			850.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >