Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005888/T1SF3E2

Date: 15/06/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSN18199019011

Claimant Vehicle No:

SGZ9685U

Insured Vehicle No:

GBA5475B

Date of Loss: 15/05/2020

Nature of Claim: TP

Claim No:

SNM20D201937C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

SGZ9685U Reg No:

Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)

Engine No: G4FC7U205558

Reg. Date: 24/11/2007 (Man. Year: 2007) Chassis No: KMHDU41BR7U246365 Odometer: 131081 km

Colour: Maroon

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Pre-accident Condition: Handbrake (Serviceable): Engine Modification: Yes

CONDITION OF TYRES

195/60 R15 Front Tyre Size: 195/60 R15 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Michelin 6 mm Rear Right Side: Michelin 6 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,818.40	2,528.40	1,290.00	33.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,960.00	380.00	16.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,158.40	4,488.40	1,670.00	27.12
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,158.40	3,600.00	2,558.40	41.54
+ GST 7.00/7.00% (S\$)	431.09	252.00	179.09	41.54
Nett Amount (S\$)	6,589.49	3,852.00	2,737.49	41.54

INSPECTION

22/05/2020 Date of Assignment:

Date Inspected: 22/05/2020 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)

38 Toh Guan Road East, #01-57,

Enterprise Hub Singapore 608581

Estimated Period of Repair: 7.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 15/6/2020

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jun 2020)

Parts: 143 HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGZ9685U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	490.00 FL	*490.00 FL
2	1		*FRONT SIDE RETAINER RH	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT FENDER RH	Bent	290.00 FL	*290.00 FL
4	1		*FRONT DOOR RH	Repair	565.00 FL	*- FL
5	1		*FRONT DOOR HANDLE	Cut	145.00 FL	*145.00 FL
6	1		*REAR DOOR RH	Bent	565.00 FL	*565.00 FL
7	1		*REAR DOOR HANDLE RH	Cut	145.00 FL	*145.00 FL
8	1		*REAR FENDER RH	Buckled	725.00 FL	*725.00 FL
9	1		*REAR BUMPER	Repair	420.00 FL	*- FL
10	1		*REAR SIDE RETAINER RH	Not Necessary	35.00 FL	*- FL
11	1		*FRONT FENDER VVTI LOGO RH	Necessary	28.00 FL	*28.00 FL
12	1		*HEADLAMP RH	Not Necessary	385.00 FL	*- FL
13	1		*SIDE MIRROR COVER RH	Repair	170.00 FL	*- FL
14	1		*FRONT RIM RH	Cut	350.00 FL	*350.00 FL
15	1		*REAR RIM RH	Cut	350.00 FL	*350.00 FL
16	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
17	1		*REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,758.00	3,153.00
	- List Item Discount on L Items 20.00/20.00% (S\$)			939.60	624.60	
				Total Parts (S\$)	3,818.40	2,528.40

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	800.00					
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIREI	New O	1,200.00	1,100.00					
3	TO REMOVE AND RE-FIT WIRING AND CHECK ALL ELECTRICAL COMPONENTS	New	80.00	30.00					
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREA	New	60.00	30.00					
	Gross Labour Cost (S\$)		2,340.00	1,960.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >