

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20005893/AYF3E2

**Date:** 18/06/2020

### REFERENCE

Insured/Claimant:	SHEN FENGMING	Policy No:	1700073068	
Date of Loss:	14/05/2020	Nature of Claim:	OD	Claim No: 0591876710SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT5837Y			
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR044427	
Reg. Date:	01/11/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ4M4HD058239	
Colour:	Grey	Odometer:	40815 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$185,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,986.00	3,742.00	4,244.00	53.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,902.00	2,652.00	2,250.00	45.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,888.00</b>	<b>6,394.00</b>	<b>6,494.00</b>	<b>50.39</b>
<b>- Excess (\$\$)</b>	<b>4,000.00</b>	<b>4,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>8,888.00</b>	<b>2,394.00</b>	<b>6,494.00</b>	<b>73.06</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>622.16</b>	<b>167.58</b>	<b>454.58</b>	<b>73.06</b>
<b>Nett Amount (\$\$)</b>	<b>9,510.16</b>	<b>2,561.58</b>	<b>6,948.58</b>	<b>73.06</b>

### INSPECTION

Date of Assignment:	22/05/2020	
Date Inspected:	22/05/2020 Inspected At:	24 BENOI SECTOR
		Repairer : Premium Automobiles Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$809.00 NETT)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TOP BUMPER	Repair	1,156.00 FS	*- FS
2	1		*REAR MIDDLE BUMPER	Deformed	1,730.00 FS	*1,730.00 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	196.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	1,188.00 FS	*1,188.00 FS
5	1		*REAR BUMPER SPOILER	Deformed	100.00 FS	*100.00 FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	361.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	1,278.00 FS	*- FS
8	1		*REAR BUMPER HOLDING STRAP	*Check	172.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	134.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR-INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Necessary	14.00 FS	*14.00 FS
12	2		*REAR WHEEL COVER-LH/RH	Necessary	710.00 FS	*710.00 FS
13	1		*EXHAUST TAIL PIPE TRIM-RH	Not Necessary	310.00 FS	*- FS
14	1		*TAIL LIGHT-RH	*Check	337.00 FS	*- FS
15	1		*SUNDRIES	*Check	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>7,986.00      3,742.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
3	TO RESPRAY REAR BUMPER,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>4,902.00</b>	<b>2,652.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**