Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005895/KEA3Q2

**Date:** 15/09/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100405123

Claimant
Vehicle No: Insured Vehicle No: EJ113X

Date of Loss: 20/05/2020 Nature of Claim: TP Claim No: 4109731575SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMP4853R

Make & Model: ALFA ROMEO GT, 2.0 JTS Engine No: 1067486

Reg. Date: 27/09/2019 (Man. Year: 2019) Chassis No: ZAREAELN7K7617189

Colour: White Odometer: 8823 km

Engine Capacity: 1995 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R19 Rear Tyre Size: 255/33 R19
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,114.73	1,075.90	3,038.83	73.85
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,220.00	530.00	690.00	56.56
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	5,334.73	1,605.90	3,728.83	69.90
	+ GST 7.00/7.00% (S\$)	373.43	112.41	261.02	69.90
	Nett Amount (S\$)	5,708.16	1,718.31	3,989.85	69.90
	0 - D - 1 - 1 (0 0 - 00400 0011)		005.00		

+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$) 385.20 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 2,105.51

**INSPECTION** 

Date of Assignment: 22/05/2020

Date Inspected: 26/05/2020 Inspected At: City Auto Pte Ltd ( Sin Ming) (HQ)

Block 8 Sin Ming Road #01-58/60/62

Sin Ming Est Singapore 575643

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,540.00 FL	*- FL
2	4		*REAR BUMPER SENSOR	Serviceable	378.00 FL	*-FL
3	1		*REAR BUMPER DIFFUSER	Dented	1,148.00 FL	*1,148.00 FL
4	1		*EXHAUST SILENCER	Repair	1,446.00 FL	*-FL
5	1		*EXHAUST MUFFLER CHROME-LH	Dented	196.88 FL	*196.88 FL
6	1		*REAR REFLECTOR LH	Serviceable	37.95 FL	*- FL
7	1		*REAR BUMPER SPONGE	Serviceable	98.20 FL	*- FL
8	1		*REAR BUMPER BRACKET UPPER	Repair	27.30 FL	*- FL
9	1		*REAR BUMPER BRACKET LOWER	Repair	95.20 FL	*- FL
10	1		*REAR BUMPER CENTRE REINFORCEMENT	Repair	175.88 FL	*-FL
F=Fra	ınchise	part. L=ListIt		Sub Total (S\$)	5,143.41	1,344.88
			- List Item Discount on L Items 2	.0.00/20.00% (S\$)	1,028.68	268.98
				Total Parts (S\$)	4,114.73	1,075.90
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHANGE EXHAUST MUFFLER	New	120.00	0.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	450.00	280.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	650.00	250.00
	Gross Labour Cost (S\$)		1,220.00	530.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >