

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20005901/FPS3Q2

**Date:** 15/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800051853

**Claimant**  
**Vehicle No :** SHC2617Y **Insured Vehicle No :** SLZ1472K

Date of Loss: 21/05/2020 Nature of Claim: TP Claim No: 2815484339SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC2617Y</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B85532
Reg. Date:	07/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU903077902
Colour:	Blue	Odometer:	156868 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,474.31	2,474.30	0.01	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,600.00	90.00	5.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,164.31</b>	<b>4,074.30</b>	<b>90.01</b>	<b>2.16</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	291.50	285.20	6.30	2.16
<b>Nett Amount (\$\$)</b>	<b>4,455.81</b>	<b>4,359.50</b>	<b>96.31</b>	<b>2.16</b>
<b>+ Loss of Use (6.0 x \$50.00/day) (\$\$)</b>		300.00		
		<b>(S\$)</b>		
		4,659.50		
<b>Liabile Amount (50.00%) (\$\$)</b>		<b>2,329.75</b>		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>2,337.24</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>2,330.00</b>		

### INSPECTION

Date of Assignment: 22/05/2020

Date Inspected: 22/05/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 4.0 days

---

**Adjuster:** PARASURAM SHANMUGAM**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY FRON	Buckled	1,264.00 FL	*1,264.00 FL
2	1		*PANEL SUB-ASSY RR D	Dented	1,258.30 FL	*1,258.30 FL
3	1		*(I40) FRT DOOR LOGO SONATA	Necessary	75.00 FS	*75.00 FS
4	1		*APP LOGO REAR DOOR L/R CT	Necessary	80.00 FS	*80.00 FS
5	1		*MLDG ASSY BODY ROCK	Cracked / Scratched	570.11 FL	*570.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,247.41</b>	<b>3,247.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	773.10	773.10

<b>Total Parts (\$\$)</b>	<b>2,474.31</b>	<b>2,474.30</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING (REPAIR RR FENDER LH)	New	600.00	600.00
2	SPRAYPAINT ON AFFECTED AREA	New	800.00	750.00
3	TUFF COAT ON AFFECTED PARTS	New	50.00	50.00
4	TRANSFER OF DOOR FRT LH	New	120.00	100.00
5	TRANSFER OF DOOR REAR LH	New	120.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,690.00</b>	<b>1,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >