

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005902/FDS3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900018208

Claimant
Vehicle No : SHD6505E **Insured Vehicle No :** SMJ929P

Date of Loss: 21/05/2020 Nature of Claim: TP Claim No: 2052971108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6505E				
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)		Engine No:	G4LEKU405244	
Reg. Date:	23/01/2020 (Man. Year: 2019)		Chassis No:	KMHC851CVLU188934	
Colour:	Blue		Odometer:	41241 km	
Engine Capacity:	1580 cc				
Market Value/New Car Price:	N/A				
Sum Insured (\$\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 10 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 10 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	934.78	361.00	573.78	61.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	530.00	430.00	44.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,894.78	891.00	1,003.78	52.98
+ GST 7.00/7.00% (\$\$)	132.63	62.37	70.26	52.97
Nett Amount (\$\$)	2,027.41	953.37	1,074.04	52.98
+ Loss of Use (1.5 x S\$50.00/day) (\$\$)		75.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		1,035.86		
Global Sum Settlement (\$\$)		1,030.00		

INSPECTION

Date of Assignment: 22/05/2020

Date Inspected: 22/05/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
3	2		*REAR BUMPER SIDE BRACKET RH/LH	Not Necessary	66.20 FL	*- FL
4	10		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,134.55	451.25
- List Item Discount on L Items 20.00/20.00% (S\$)	199.77	90.25
Total Parts (S\$)	934.78	361.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	240.00
2	SPRAY PAINTING CHARGE	New	280.00	200.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (\$\$)			960.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >