



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005118
INV Date 21/07/2020
Reference CC6/CTI20005911/Aga3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SME 38L
Insured Veh. SLR 6020R
Claim No. SNM20D201990
Policy No. DMPCSN1932191900
Accident Date 22/05/2020
Inspection Date 26/05/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20005911/Aga3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 6020R	Veh. Inspected	SME 38L
Policy No.	DMPCSN1932191900	Coverage (\$)	0.00
Claim No.	SNM20D201990	Excess (\$)	0.00
Assign From		Assign Date	26/05/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN TEANA	c.c	2010
Engine No.	HIDDEN	Year of Reg.	1997
Chassis No.	JN1BDUJ32Z0001350	Colour	BLACK
Odometer	165899	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	6 mm
L/H Front Tyre	215/60 R16	FALKEN	6 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/05/2020	Inspection Date	26/05/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 38L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,090.20	-
2	FRONT BONNET HINGE @\$41.80	NOT NECESSARY	83.60	-
1	FRONT GRILLE	BENT	562.60	562.60
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	20.00
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	80.90	80.90
1	FRONT GRILLE CHROME	CUT	120.20	120.20
2	FRONT HEADLAMP @\$654.70	CUT	1,309.40	1,309.40
2	FRONT HEADLAMP LOWER BRACKET @\$28.10	NOT NECESSARY	56.20	-
1	FRONT BUMPER	DISTORTED	720.00	720.00
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$32.10	NECESSARY	64.20	64.20
2	FRONT BUMPER FOG LAMP @\$323.70	CRACKED	647.40	647.40
2	FRONT BUMPER FOG LAMP COVER @\$130.10	N/S DEFORMED	260.20	130.10
2	FRONT BUMPER FOG LAMP CHROME @\$62.20	NOT NECESSARY	124.40	-
1	FRONT BUMPER NUMBER PLATE	BENT	50.00	50.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	38.50	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	80.50	-
1	FRONT BUMPER TOP BEAM	BENT	179.00	179.00
1	FRONT BUMPER REINFORCEMENT	DENTED	369.10	369.10
1	FRONT BUMPER INNER FOAM	CRACKED	291.60	291.60
1	FRONT BUMPER UNDER COVER	TORN	199.70	199.70
2	FRONT FENDER COWLING @\$99.40	TORN	198.80	198.80
16	FRONT FENDER COWLING CLIP @\$6.50	NECESSARY	104.00	60.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	746.10	-
1	FRONT AIR-CONDENSER	DENTED	517.90	517.90
1	FRONT RADIATOR	NOT NECESSARY	834.80	-
1	FRONT RADIATOR FAN MOTOR	NOT NECESSARY	984.70	-
	LESS 10% DISCOUNT		-	-555.09
			9,831.00	4,995.81

Report Ref No. CC6/CTI20005911/Aga3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS.		280.00	120.00
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE.		100.00	60.00
	TOWING .		150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET .		1,600.00	500.00
	SPRAY PAINTING.		1,400.00	600.00
			3,630.00	1,370.00
	GRAND TOTAL		13,461.00	6,365.81
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,100.00

Report Ref No. CC6/CTI20005911/Aga3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 38L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SME 38L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

