

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005913/UPA3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100359288

Claimant
Vehicle No : FBG8259H **Insured Vehicle No :** SJJ4515J

Date of Loss: 02/05/2020 Nature of Claim: TP Claim No: 5441981264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG8259H	Engine No:	DN806507
Make & Model:	SYM VS150A, 150cc	Chassis No:	RFGHV15WYCS004764
Reg. Date:	30/11/2012 (Man. Year: 2012)	Odometer:	76628 km
Colour:	White		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-12	Rear Tyre Size:	120/70-12
Front Left Side:	IRC 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,396.40	1,183.86	2,212.54	65.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	662.00	600.00	62.00	9.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,058.40	1,783.86	2,274.54	56.05
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	4,058.40	1,400.00	2,658.40	65.50
+ GST 7.00/7.00% (S\$)	284.09	98.00	186.09	65.50
Nett Amount (S\$)	4,342.49	1,498.00	2,844.49	65.50
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,598.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOARD FLOOR	Cut	44.50 F	*44.50 FL
2	1		*COVER INNER MUDGUARD REAR	Broken	22.30 F	*22.30 FL
3	1		*BALANCER HANDLE	Scratched	15.00 F	*15.00 FL
4	1		*BALL STEEL	Not Necessary	0.50 F	*- FL
5	1		*BEARING STEERING CONE UPPER	Not Necessary	7.50 F	*- FL
6	1		*BELLY PAN (BLACK)	Cut	131.80 F	*131.80 FL
7	1		*BOX REAR FIBRE STD (23X18X18) TL-V2-VAIVED	Repair	430.00 F	*- FL
8	1		*BRACKET UNDER FORK	Serviceable	178.20 F	*- FL
9	1		*COVER FRONT (WHITE)	Repair	119.00 F	*- FL
10	1		*COVER INNER FRONT	Cut	140.00 F	*140.00 FL
11	1		*COVER TAIL LH	Repair	150.00 F	*- FL
12	1		*COVER TAIL RH	Cut	150.00 F	*150.00 FL
13	1		*DUST SEAL	Not Necessary	4.20 F	*- FL
14	1		*FORK FRONT LH ASSY	Not Necessary	251.00 F	*- FL
15	1		*LEVER BRAKE RH	Scratched	20.50 F	*20.50 FL
16	1		*LIGHT TAIL ASSY	Broken	406.00 F	*406.00 FL
17	1		*MIRROR RH	Cut	67.20 F	*67.20 FL
18	1		*MUDGUARD FRONT	Repair	98.00 F	*- FL
19	1		*MUDGUARD REAR	Broken	27.00 F	*27.00 FL
20	1		*PIPE EXHAUST ASSY	Repair	812.00 F	*- FL
21	1		*RACE BALL	Not Necessary	10.80 F	*- FL
22	1		*RACE BALL	Not Necessary	10.80 F	*- FL
23	1		*RACE BOTTOM CONE	Not Necessary	9.80 F	*- FL
24	1		*REFLECTOR MUDGUARD REAR	Broken	8.00 F	*8.00 FL
25	1		*SEAL DUST WASHER	Not Necessary	4.20 F	*- FL
26	1		*SHOCK ABSORBER REAR LH	Bent	111.50 F	*111.50 FL
27	1		*SHOCK ABSORBER REAR RH	Bent	79.60 F	*79.60 FL
28	1		*SIDE COVER LOWER RH	Necessary	42.00 F	*42.00 FL
29	1		*STICKER (SINGAPORE POST) BOX REAR	Necessary	30.00 FS	*30.00 FS
30	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Broken	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,396.40	1,310.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	126.54
Total Parts (\$\$)	3,396.40	1,183.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	360.00	300.00
2	BALL BEARING-FOR DISMANTLE AND ASSEMBLING PARTS QUOTED	New	2.00	0.00
3	SPRAY PAINT COVER TAIL LH	New	45.00	45.00
4	SPRAY PAINT MUDGUARD FRONT	New	45.00	45.00
5	SPRAY PAINT REAR BOX	New	210.00	210.00
Gross Labour Cost (\$\$)			662.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >