

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005914/UGA3Q2

Date: 08/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant
Vehicle No : FBN4928A **Insured Vehicle No :** SLV3207T

Date of Loss: 18/09/2019 Nature of Claim: TP Claim No: 1314316708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN4928A		
Make & Model:	PIAGGIO VESPA SPRINT 150, 155cc SPORT	Engine No:	MA14M1000918
Reg. Date:	15/10/2018 (Man. Year: 2018)	Chassis No:	ZAPMA140000001967
Colour:	Yellow	Odometer:	1175 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-70-12	Rear Tyre Size:	120-70-12
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	765.50	730.50	35.00	4.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,185.00	1,345.00	53.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,295.50	1,915.50	1,380.00	41.88
+ GST 7.00/7.00% (S\$)	230.69	134.09	96.60	41.87
Nett Amount (S\$)	3,526.19	2,049.59	1,476.60	41.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HEAD FAIRING CHROME MOULDING	Cracked	75.00 FL	*75.00 FL
2	2		*SIDE MIRROR ASSY	Scratched	320.00 FL	*320.00 FL
3	1		*REAR EXHAUST CHROME PROTECTOR COVER	Scratched	85.00 FL	*85.00 FL
4	1		*O/S SIDE FAIRING CHROME MOULDING	Broken	65.00 FL	*65.00 FL
5	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*15.00 FS
6	1		*FRONT VISOR	Scratched	250.00 FL	*250.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	845.00	810.00
- List Item Discount on L Items 10.00/10.00% (S\$)	79.50	79.50
Total Parts (S\$)	765.50	730.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	80.00	35.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	0.00
3	LABOUR TO DISMANTLE FAIRING FOR FACILITE REPAIR }	New	350.00	500.00
4	LABOUR CHARGES }	New	850.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	650.00
Gross Labour Cost (\$\$)			2,530.00	1,185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >