

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005919/KBA3Q2

Date: 26/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494440

Claimant
Vehicle No : SCW2009G **Insured Vehicle No :** SLJ6832G

Date of Loss: 21/05/2020 Nature of Claim: TP Claim No: 7441891701SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCW2009G		
Make & Model:	AUDI A3 SB, 1.4 TFSI (AMBITION) (A)	Engine No:	CMB145319
Reg. Date:	29/11/2013 (Man. Year: 2013)	Chassis No:	WAUZZZ8V4DA078876
Colour:	White	Odometer:	81355 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,971.50	3,599.00	2,372.50	39.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,350.00	550.00	28.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,871.50	4,949.00	2,922.50	37.13
Approved Total (Overridden) (\$\$)		3,950.00		
(\$\$)	7,871.50	3,950.00	3,921.50	49.82
+ GST 7.00/7.00% (\$\$)	551.01	276.50	274.51	49.82
Nett Amount (\$\$)	8,422.51	4,226.50	4,196.01	49.82
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,828.50		
Global Sum Settlement (\$\$)		4,700.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020 Inspected At:

City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01., Sin Ming
AutoCity,
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,350.00 FL	*1,350.00 FL
2	1		*FRONT LH DOOR OUTER HANDLE	Distorted	240.00 FL	*240.00 FL
3	1		*FRONT LH DOOR OUTER HANDLE CAP	Serviceable	35.00 FL	*- FL
4	1		*FRONT LH DOOR OUTER HANDLE KEYLESS ANTENNA	Serviceable	290.00 FL	*- FL
5	1		*FRONT LH DOOR OUTER HANDLE BRACKET	Repair	40.00 FL	*- FL
6	1		*FRONT LH DOOR LOCK	Repair	390.00 FL	*- FL
7	1		*FRONT LH DOOR WEATHERSTRIP (50%)	Necessary	198.00 FS	*110.00 FS
8	1		*FRONT LH DOOR REGULATOR	Bent	320.00 FL	*320.00 FL
9	1		*FRONT LH DOOR REGULATOR MOTOR	Jammed	550.00 FL	*550.00 FL
10	1		*FRONT LH DOOR OUTER MOULDING	Serviceable	140.00 FL	*- FL
11	1		*FRONT LH DOOR CONTROL UNIT	Serviceable	350.00 FL	*- FL
12	10		*FRONT LH DOOR RIVET	Necessary	30.00 FL	*30.00 FL
13	1		*FRONT LH DOOR TRIMBOARD	Serviceable	1,050.00 FL	*- FL
14	2		*REAR LH DOOR HINGE	Repair	190.00 FL	*- FL
15	1		*REAR LH DOOR	Bent	1,320.00 FL	*1,320.00 FL
16	1		*REAR LH DOOR RUBBER (50%)	Necessary	108.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,601.00	3,980.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	629.50	381.00
Total Parts (\$\$)	5,971.50	3,599.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT DOOR GLASS ,AND OTHERS RELATED PARTS TO NEW DOORS	New	180.00	120.00
2	TO USE DIAGNOSTIC COMPUTER TO CHECK AND RESET THE SETTINGS	New	120.00	80.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	700.00	550.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	900.00	600.00
Gross Labour Cost (\$\$)			1,900.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >