

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20005922/KBA3Q2

**Date:** 19/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993934

**Claimant**  
**Vehicle No :** SDM6011M **Insured Vehicle No :** SKK6858P

Date of Loss: 25/02/2020 Nature of Claim: TP Claim No: 3271289950SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM6011M		
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Engine No:	27492031076374
Reg. Date:	23/11/2017 (Man. Year: 2017)	Chassis No:	WDD2050422R312599
Colour:	Metallic Black	Odometer:	76344 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,123.00	2,907.00	13,216.00	81.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	440.00	2,560.00	85.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,123.00</b>	<b>3,347.00</b>	<b>15,776.00</b>	<b>82.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>(S\$)</b>	19,123.00	2,700.00	16,423.00	85.88
<b>+ GST 7.00/7.00% (S\$)</b>	1,338.61	189.00	1,149.61	85.88
<b>Nett Amount (S\$)</b>	<b>20,461.61</b>	<b>2,889.00</b>	<b>17,572.61</b>	<b>85.88</b>
<b>+ Car Rental (3.0 x S\$180.00/day + 7.00% GST) (S\$)</b>		577.80		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>3,495.80</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,400.00</b>		

### INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 14/07/2020 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)  
176 Sin Ming Drive #01-15, Sin Ming  
AutoCare  
Singapore 575721

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked / Bent	1,700.00 FL	*1,700.00 FL
2	1		*FRONT BUMPER SPONGE	Serviceable	185.00 FL	*- FL
3	1		*FRONT BUMPER SEALING ,FR-END ASSEMBLY	Serviceable	65.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	500.00 FL	*- FL
5	1		*FRONT BUMPER TOWING COVER	Serviceable	95.00 FL	*- FL
6	1		*FRONT BUMPER BASIC CARRIER RH	Serviceable	90.00 FL	*- FL
7	1		*FRONT BUMPER BASIC CARRIER BOTTOM	Serviceable	150.00 FL	*- FL
8	1		*FRONT BUMPER BASIC CARRIER TOP	Serviceable	100.00 FL	*- FL
9	1		*FRONT BUMPER COVER RH	Serviceable	80.00 FL	*- FL
10	1		*FRONT BUMPER RADAR SENSOR	Serviceable	1,200.00 FL	*- FL
11	1		*SET FRONT BUMPER SENSOR	Serviceable	200.00 FL	*- FL
12	10		*FRONT BUMPER RIVET	Necessary	80.00 FL	*80.00 FL
13	1		*HEAD LAMP RH	Mtg Cracked	1,400.00 FL	*1,400.00 FL
14	1		*HEAD LAMP RH GASKET	Cracked	50.00 FL	*50.00 FL
15	1		*BONNET	Repair	2,600.00 FL	*- FL
16	1		*BONNET DAMPING HOOD	Serviceable	300.00 FL	*- FL
17	1		*BONNET SAFETY HOOK	Serviceable	100.00 FL	*- FL
18	1		*BONNET ROUND MERCEDES DECAL	Not Necessary	95.00 FL	*- FL
19	1		*RH FENDER	Repair	1,250.00 FL	*- FL
20	1		*RH FENDER COVER	Serviceable	30.00 FL	*- FL
21	1		*RH FENDER WHEEL ARCH UNDER COVER	Serviceable	150.00 FL	*- FL
22	1		*RH FENDER WHEEL ARCH COVER	Serviceable	150.00 FL	*- FL
23	1		*RH FRONT KNUCKLE ARM	Serviceable	1,400.00 FL	*- FL
24	1		*RH FRONT KNUCKLE ARM STRUT ROD	Serviceable	700.00 FL	*- FL
25	1		*RH FRONT KNUCKLE ARM SPRING LINK	Serviceable	700.00 FL	*- FL
26	1		*RH FRONT KNUCKLE ARM TRANSV ,CONTROL ARM RH	Serviceable	900.00 FL	*- FL
27	1		*RH FRONT KNUCKLE ARM WHEEL BEARING	Not Necessary	600.00 FL	*- FL
28	1		*RH TYRE	Serviceable	290.00 FS	*- FS
29	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS
30	1		*RH FRONT RIM	Serviceable	1,800.00 FS	*- FS
31	1		*CERAMIC COATING	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 17,610.00    3,230.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 1,487.00    323.00

**Total Parts (\$\$)** 16,123.00    2,907.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,400.00	220.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
3	TO REMOVE & REFIT FRONT RH UNDERCARRIAGE	New	250.00	0.00
4	TO REMOVE ,RENEW & REFIT FRONT RH TYRE	New	40.00	0.00
5	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	150.00	0.00
6	TO APPLY ANTI RUSTING COATING	New	80.00	0.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>3,000.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >