Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005928/R1VF3E2

Date: 04/06/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993880

Claimant Vehicle PA7778Z Insured Vehicle No: GBG8278C

Date of Loss: 26/07/2018 Nature of Claim: TP Claim No: 1257950248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA7778Z

Make & Model: ISUZU LV434R, 7.8 D (M) Engine No: 6HK1620575

Reg. Date: 03/05/2012 (Man. Year: 2012) Chassis No: JALLV434CC7000013

Colour: Multi-colour Odometer: 291463 km

Engine Capacity: 7790 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)

Front Left Side: Golden Crown 8 mm Rear Left Side: Golden Crown 8/8 mm Front Right Side: Golden Crown 8 mm Rear Right Side: Golden Crown 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/05/2020

Date Inspected: 28/05/2020 Inspected At: Sts Transport Management Pte Ltd (HQ)

15 PIONEER SECTOR 2

Singapore 628376

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE	Scratched	0.00 F	*- F
2	1	*REAR BUMPER	Cracked	0.00 F	*- F
3	1	*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
4	1	*TAILGATE	Repair	0.00 F	*- F
F=Fra	anchise part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmitted	I during this print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >