

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20005932/ABA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00001179

Claimant
Vehicle No : SMD2312L **Insured Vehicle No :** SGF2422M

Date of Loss: 23/05/2020 **Nature of Claim:** TP **Claim No:** 1202000017970

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2312L		
Make & Model:	KIA CERATO K3, 1.6 (A)	Engine No:	G4FGHH679256
Reg. Date:	23/08/2017 (Man. Year: 2017)	Chassis No:	KNAFX411MJ5742058
Colour:	Blue	Odometer:	36274 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,430.00	3,586.50	4,843.50	57.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,540.00	1,800.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,770.00	5,126.50	6,643.50	56.44
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	11,770.00	4,100.00	7,670.00	65.17
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		4,460.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6,
#01-43
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD2312L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	1,297.00 F	*- FL
2	2		*REAR BOOT LID HINGE	Not Necessary	132.00 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	170.00 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	48.00 F	*48.00 FL
5	1		*REAR BOOT LID FORTE LOGO	Necessary	43.00 F	*43.00 FL
6	1		*REAR BOOT LID K3 LOGO	Necessary	40.00 F	*40.00 FL
7	1		*REAR BOOT LID C&C LOGO	Necessary	55.00 F	*55.00 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	70.00 F	*- FL
10	1		*REAR BOOT LID SIDE REFLECTOR	O/S Cut	354.00 F	*177.00 FL
11	1		*REAR BOOT LID LOCK	Not Necessary	122.00 F	*- FL
12	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	98.00 F	*- FL
13	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	225.00 F	*- FL
14	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
15	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
16	1		*REAR TAILLAMP	O/S Cut	1,392.00 F	*696.00 FL
17	4		*REAR TAILLAMP CLIP	Not Necessary	32.00 F	*- FL
18	2		*REAR TAILLAMP PANEL	Not Necessary	206.00 F	*- FL
19	1		*REAR BUMPER	Deformed	688.00 F	*688.00 FL
20	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
21	1		*REAR BUMPER LOWER LID	Deformed	286.00 F	*286.00 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	76.00 F	*76.00 FL
23	1		*REAR BUMPER SIDE REFLECTOR	O/S Cracked	228.00 F	*114.00 FL
24	2		*REAR BUMPER REVERSE SENSOR	Damaged	310.00 F	*310.00 FL
25	1		*REAR BUMPER REINFORCEMENT	Cracked	338.00 F	*338.00 FL
26	1		*REAR END PANEL	Dented	385.00 F	*385.00 FL
27	1		*REAR END PANEL TOP GARNISH	Cracked	108.00 F	*108.00 FL
28	1		*REAR EXHAUST	Bent	880.00 F	*591.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,430.00	3,985.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	398.50
Total Parts (\$\$)	8,430.00	3,586.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	GUM	New	60.00	0.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	180.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	60.00
6	TOWING FEE	New	150.00	0.00
7	PANEL BEATING	New	1,400.00	700.00
8	SPRAY PAINTING	New	1,200.00	700.00
Gross Labour Cost (\$\$)			3,340.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >