

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17006132/KEA3Q2-1

Date: 09/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100285470

Claimant
Vehicle No : SHB7566H **Insured Vehicle No :** SJU1882K

Date of Loss: 25/03/2017 Nature of Claim: TP Claim No: 0728658067SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7566H	Engine No:	Z20S1450735K
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJBB078199
Reg. Date:	20/04/2012 (Man. Year: 2011)	Odometer:	854387 km
Colour:	Red/White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Linglong 7 mm	Rear Left Side:	Linglong 7 mm
Front Right Side:	Linglong 7 mm	Rear Right Side:	Linglong 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,566.73	1,846.20	5,720.53	75.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,730.00	420.00	6,310.00	93.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,296.73	2,266.20	12,030.53	84.15
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	14,296.73	1,800.00	12,496.73	87.41
+ GST 7.00/7.00% (\$\$)	1,000.77	126.00	874.77	87.41
Nett Amount (\$\$)	15,297.50	1,926.00	13,371.50	87.41
+ Car Rental (2.0 x S\$71.39/day) (\$\$)		142.78		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		2,076.27		
Global Sum Settlement (\$\$)		2,070.00		

INSPECTION

Date of Assignment: 28/03/2017

Date Inspected: 28/03/2017 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,202.00 FL	*1,202.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	295.25 FL	*- FL
3	1		*FRONT BUMPER LOWER ABSORBER	Serviceable	180.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP OUTER COVER LH	Serviceable	32.40 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Serviceable	78.00 FL	*- FL
6	1		*FRONT BUMPER LOWER STIFFENER	Repair	134.37 FL	*- FL
7	1		*FRONT BUMPER RETAINER LH	Serviceable	102.00 FL	*- FL
8	1		*FRONT BUMPER RETAINER RH	Serviceable	102.00 FL	*- FL
9	1		*FRONT HEADLAMP LH	Cracked	816.00 FL	*816.00 FL
10	1		*FRONT FENDER LH	Repair	837.60 FL	*- FL
11	1		*FRONT FENDER LINER LH	Serviceable	47.00 FL	*- FL
12	1		*RESONATOR (B/S FENDER LH) AIR BOX	Serviceable	134.67 FL	*- FL
13	1		*RESONATOR HOSE	Serviceable	37.00 FL	*- FL
14	1		*RADIATOR GRILLE (GRILLE A-RAD)	Serviceable	367.00 FL	*- FL
15	1		*BONNET	Repair	1,250.00 FL	*- FL
16	1		*BONNET HINGE RH	Repair	36.00 FL	*- FL
17	1		*BONNET HINGE LH	Repair	36.00 FL	*- FL
18	1		*BONNET MOULDING	Serviceable	161.97 FL	*- FL
19	1		*FRONT SIDE VIEW MIRROR LH	Serviceable	939.00 FL	*- FL
20	1		*SET FRONT BUMPER FASTENER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	192.00 FS	*- FS
22	1		*SET RADIATOR GRILLE TOP COVER CLIP	Not Necessary	10.00 FS	*- FS
23	1		*SET RADIATOR GRILLE CLIP	Not Necessary	35.00 FS	*- FS
24	1		*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*- FS
25	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
26	1		*FRONT TYRE LH	Serviceable	360.00 FS	*- FS
27	1		*FRONT WHEEL RIM LH	Serviceable	254.00 FS	*- FS
28	1		*FRONT WHEEL RIM HUB CAP LH	Serviceable	166.30 FS	*- FS
29	1		*FRONT FENDER ADVERTISEMENT STICKER LH	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,245.56	2,048.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	678.83	201.80
Total Parts (\$\$)	7,566.73	1,846.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	220.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,700.00	200.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TOWING FEES	New	120.00	0.00
8	TO REMOVE AND REPLACE CORPORATE STICKER	New	330.00	0.00
Gross Labour Cost (\$\$)			6,730.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >