

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20005948/AGA3Q2

Date: 20/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00011653-01

Claimant
Vehicle No : GBA7947T **Insured Vehicle No :** SKJ4872R

Date of Loss: 24/05/2020 **Nature of Claim:** TP **Claim No:** 1202000018051

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA7947T		
Make & Model:	NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)	Engine No:	ZD30153098K
Reg. Date:	19/01/2008 (Man. Year: 2007)	Chassis No:	JN1MG4E25Z0780421
Colour:	Gold	Odometer:	179920 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	GREEN-MAX 6 mm	Rear Left Side:	GREEN-MAX 6 mm
Front Right Side:	GREEN-MAX 6 mm	Rear Right Side:	GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,430.23	1,690.35	739.88	30.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	610.00	630.00	50.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,670.23	2,300.35	1,369.88	37.32
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,670.23	1,800.00	1,870.23	50.96
+ GST 7.00/7.00% (S\$)	256.92	126.00	130.92	50.96
Nett Amount (S\$)	3,927.15	1,926.00	2,001.15	50.96
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		2,273.45		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
KAKI BUKIT AUTOHUB 2 KAKI

BVUKIT AVE 2 #01-18
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jul 2020)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA7947T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	492.90 FL	*347.00 FL
2	1		*FRONT GRILLE LOGO EMBLEM	Necessary	87.90 FL	*87.90 FL
3	1		*FRONT LH HEADLAMP	Cracked	497.80 FL	*497.80 FL
4	1		*FRONT LH SIGNAL LAMP	Cracked	129.00 FL	*129.00 FL
5	1		*FRONT BUMPER	Deformed	629.10 FL	*629.10 FL
6	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	258.00 FL	*- FL
7	1		*FRONT BUMPER LH FOGLAMP GARNISH	Cut	120.70 FL	*120.70 FL
8	1		*FRONT LH STEP GARNISH	Repair	329.30 FL	*- FL
9	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
10	1		*SET FRONT LH HEADLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
11	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*SET FRONT LH STEP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,684.70	1,871.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	254.47	181.15
Total Parts (\$\$)	2,430.23	1,690.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSSING (TO FR)	New	80.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	280.00
3	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	300.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	60.00	0.00
Gross Labour Cost (\$)			1,240.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >