

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 6509P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LH DOOR PANEL	DENTED / SCRATCHED	1,080.00	965.95
1	FRONT LH DOOR LOCK ASSY	NOT NECESSARY	420.00	-
1	REAR LH DOOR PANEL	DENTED / SCRATCHED	1,130.00	840.30
1	REAR LH DOOR LOCK ASSY	DAMAGED	481.00	357.00
1	REAR LH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-622.20	-432.65
			2,488.80	1,730.60
	SPECIAL NETT ITEMS			
1	SET FRONT DOOR INNER TRIM CLIP (SN)	NECESSARY	30.00	20.00
1	SET REAR DOOR INNER TRIM CLIP (SN)	NECESSARY	30.00	20.00
			60.00	40.00
	LABOUR			
	CHECK WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE, REFIT LINING, TRIM AND GARNISH.		100.00	50.00
	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW.		200.00	90.00
	TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEW.		200.00	90.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR LH FENDER.		800.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	550.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	50.00
			-	-
			-	-
			-	-
			2,480.00	1,360.00
	GRAND TOTAL		5,028.80	3,130.60

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00	

Report Ref No. CS3/III20002551/Fvf3s2-1





Report Ref No. CS3/III20002551/Fvf3s2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

X:2.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.