



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20002551/Fvf3s2-1

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 01-06-2020



Code : III2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |             |                       |            |
|---------------------|-------------|-----------------------|------------|
| <b>Insured Veh.</b> | SHD 7212T   | <b>Veh. Inspected</b> | SKC 6509P  |
| <b>Policy No.</b>   | MCOM0015    | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | MCT20010577 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | DERRICK TAN | <b>Assign Date</b>    | 27/05/2020 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |          |
|-------------------------|-------------------|---------------------|----------|
| <b>Make &amp; Model</b> | SUBARU IMPREZA    | <b>c.c</b>          | 1498     |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2010     |
| <b>Chassis No.</b>      | JF1GH3KS59G035389 | <b>Colour</b>       | BLUE     |
| <b>Odometer</b>         | 185048            | <b>Steering</b>     | IN ORDER |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | NIL      |
| <b>General</b>          | GOOD              |                     |          |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 225/45 R18  | GOODYEAR    | 5 mm           |
| <b>L/H Front Tyre</b> | 225/45 R18  | GOODYEAR    | 5 mm           |
| <b>R/H Rear Tyre</b>  | 225/45 R18  | GOODYEAR    | 5 mm           |
| <b>L/H Rear Tyre</b>  | 225/45 R18  | GOODYEAR    | 5 mm           |

### 4. Description of Damages

|                                                                        |
|------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------|

### 5. General Information

|                       |                                                                                         |                        |            |
|-----------------------|-----------------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 24/01/2020                                                                              | <b>Inspection Date</b> | 14/02/2020 |
| <b>Survey held at</b> | GV MOTORWORKS PTE LTD<br>68 KAKI BUKIT AVE 6 #01-10 ARK@KB, KAKI BUKIT 417896 SINGAPORE |                        |            |

### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>4 Working Days</b> |
|-------------------------------------|-----------------------|