

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005957/AGA3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900155920
Claimant Vehicle No :	SJY6286C	Insured Vehicle No :	SJT9112C
Date of Loss:	22/05/2020	Nature of Claim:	TP
		Claim No:	1133614918SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6286C	Engine No:	G4FCAH231533
Make & Model:	KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A)	Chassis No:	KNAFU411MA5283971
Reg. Date:	20/09/2010 (Man. Year: 2010)	Odometer:	118435 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,627.00	4,063.00	3,564.00	46.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,740.00	1,070.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,437.00	5,803.00	4,634.00	44.40
Approved Total (Overridden) (S\$)		4,000.00		

Nett Amount (S\$)	10,437.00	4,000.00	6,437.00	61.67
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		4,800.00		

INSPECTION

Date of Assignment: 26/05/2020

Date Inspected: 26/05/2020

Estimated Period of Repair: 6.0 days

Inspected At:

UNIMOTOR COMPANY
NO 1 KAKI BUKIT AVE 6 #01-94
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FACE	Deformed	607.00 F	*607.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Cracked	356.00 F	*356.00 FL
3	1		*REAR BUMPER REINFORCEMENT BRACKET	O/S Bent	170.00 F	*85.00 FL
4	2		*REAR BUMPER SIDE METAL BRACKET	Not Necessary	44.00 F	*- FL
5	2		*REAR BUMPER SIDE RETAINER BRACKET	Necessary	70.00 F	*70.00 FL
6	1		*REAR BUMPER BLACK SPONGE	Cracked	134.00 F	*134.00 FL
7	10		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
8	1		*REAR TAIL END PANEL	Dented	482.00 F	*482.00 FL
9	1		*REAR TAILLAMP ASSY	O/S Cracked	526.00 F	*263.00 FL
10	1		*REAR BOOT ASSY	Buckled	747.00 F	*747.00 FL
11	1		*REAR BOOT LOCK	Not Necessary	113.00 F	*- FL
12	1		*REAR BOOT LOCK ACTUATOR	Not Necessary	205.00 F	*- FL
13	1		*REAR BOOT STRIKER	Not Necessary	28.00 F	*- FL
14	1		*REAR BOOT KIA EMBLEM	Necessary	32.00 F	*32.00 FL
15	1		*REAR BOOT CERATOR EMBLEM	Necessary	38.00 F	*38.00 FL
16	1		*REAR BOOT FORTE EMBLEM	Necessary	37.00 F	*37.00 FL
17	1		*REAR BOOT LIMITED EMBLEM	Necessary	35.00 F	*35.00 FL
18	2		*REAR BOOT LAMP	Not Necessary	270.00 F	*- FL
19	2		*REAR BOOT HINGES	Not Necessary	130.00 F	*- FL
20	1		*REAR BOOT WEATHERSTRIP	Cut	98.00 F	*98.00 FL
21	1		*REAR FENDER INNER SIDE LINING GARNISH	O/S Torn	550.00 F	*275.00 FL
22	1		*REAR FLOOR PANEL	Repair	633.00 F	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	686.00 F	*- FL
24	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	56.00 F	*- FL
25	1		*REAR AIR OUTLET GARNISH	Not Necessary	39.00 F	*- FL
26	1		*REAR SPARE WHEEL TOP COVER BOARD	Deformed	189.00 F	*189.00 FL
27	1		*REAR PANEL LINING GARNISH	Deformed	92.00 F	*92.00 FL
28	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
29	1		*REAR BUMPER LOWER SPOILER	Cracked	950.00 FS	*650.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,627.00	4,420.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	357.00
Total Parts (\$)	7,627.00	4,063.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR REVERSE SENSOR	New	80.00	50.00
2	TO DISM/RENEW REAR EXHAUST BOX	New	200.00	0.00
3	TO SPRAY UNDERCOATING IN REPAIR	New	150.00	60.00
4	TO DISM/REWIRE DAMAGED PORTION	New	180.00	30.00
5	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,200.00	800.00
6	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,810.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >