



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8783R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL (CONSISTENT)	CRACKED	2,070.00	2,070.00
1	GRILLE (CONSISTENT)	CRACKED	332.00	332.00
2	TRIM MOULDING @\$58.00 (CONSISTENT)	NECESSARY	116.00	116.00
1	EMBLEM (CONSISTENT)	NECESSARY	65.00	65.00
1	EMBLEM (CONSISTENT)	NECESSARY	67.00	67.00
1	CORNER PANEL (CONSISTENT)	DEFORMED	263.00	263.00
1	AIR DEFLECTOR (CONSISTENT)	MISSING	140.00	140.00
1	EMBLEM (CONSISTENT)	NECESSARY	36.00	36.00
1	RECEIVER DRIER (CONSISTENT)	DENTED	316.00	316.00
	LESS 30% DISCOUNT		-1,021.50	-1,021.50
			2,383.50	2,383.50
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE RH CORNER PANEL ,DEFLECTOR ,FRONT LID PANEL ,GRILLE & EMBLEM		1,000.00	500.00
	TO SPRAY PRIMER & SPRAY PAINT ON RH CORNER PANEL ,DEFLECTOR,FRONT LID OANEL & AFFECTED AREA .		2,200.00	1,600.00
			3,200.00	2,100.00
	GRAND TOTAL		5,583.50	4,483.50
RECOMMENDED COST OF REPAIRS				4,483.50

Report Ref No. CC4/ASM20005958/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.