



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM20005958/Tpa3q2 Date: 30/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 6573T	Veh. Inspected	XD 8783R
	Policy No.	P1969058	Coverage (\$)	0.00
	Claim No.	S0M02LVK	Excess (\$)	0.00
	Assign From		Assign Date	27/05/2020
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO FEE300	c.c	7146
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	YV2VH70D5EB686404	Colour	WHITE
	Odometer	308528 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	FIRENZA	8 mm
	L/H Front Tyre	295/80 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/04/2020	Inspection Date	27/05/2020
	Survey held at	20 ATTAP VALLEY ROAD		
	Repairer	VOLVO EAST ASIA (PTE) LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days